



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 4694D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	BADLY DENTED / TORN	481.25	481.25
1	FRONT BUMPER SIDE RETAINER N/S	BENT	131.40	131.40
1	FRONT BUMPER BRACKET N/S	NOT NECESSARY	141.55	-
1	FRONT BUMPER FOG LAMP GARNISH O/S	NOT NECESSARY	182.20	-
1	FRONT BUMPER FOG LAMP N/S	NOT NECESSARY	287.75	-
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	30.00
1	FRONT N/S FENDER 'VVTI' EMBLEM	NECESSARY	53.50	53.50
1	FRONT N/S FENDER	BADLY DENTED	581.45	581.45
1	FRONT N/S FENDER INNER SHIELD	TORN	181.90	181.90
1	SET FRONT N/S FENDER INNER SHIELD CLIPS	NECESSARY	30.00	20.00
1	WIPER SPARE TANK	NOT NECESSARY	181.25	-
1	AIR RESONATOR	RIPPED OFF	184.25	184.25
1	FRONT N/S SHOCK ABSORBER	BENT	581.40	410.00
1	FRONT N/S LOWER ARM	BENT	591.60	591.60
1	FRONT N/S KNUCKLE ARM	NOT NECESSARY	491.50	-
1	FRONT N/S DOOR	TO REPAIR SEE LABOUR	1,100.00	-
1	REAR N/S DOOR	TO REPAIR SEE LABOUR	1,079.60	-
1	REAR N/S FENDER	TO REPAIR SEE LABOUR	1,282.25	-
1	N/S HEADLAMP	CRACKED	2,816.50	2,816.50
1	FRONT GRILLE	CRACKED	381.40	381.40
	LESS 25% DISCOUNT		-	-1,465.81
			10,820.75	4,397.44
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT N/S WHEEL RIM (SN)	DENTED / WARPED	650.00	550.00
			650.00	550.00





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN FRONT N/S DOOR, REAR N/S DOOR, REAR N/S FENDER AND WHEEL ARCH, FRONT N/S INNER SUPPORT PANEL AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT N/S DOOR, REAR N/S DOOR AND REAR N/S FENDER.		1,800.00	600.00
	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS.		1,800.00	1,200.00
	CHECK ELECTRICAL.		30.00	20.00
	REWIRE FRONT N/S FENDER INNER WIRING.		200.00	30.00
	RESET WHEEL ALIGNMENT - BEFORE REPAIR.		100.00	80.00
	REMOVE AND REFIT FRONT N/S SUSPENSION.		500.00	300.00
	RESET WHEEL ALIGNMENT - AFTER REPAIRED.		100.00	80.00
	REPLACE FRONT N/S WHEEL RIM AND BALANCING.		40.00	30.00
			4,570.00	2,340.00
<b>GRAND TOTAL</b>			<b>16,040.75</b>	<b>7,287.44</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>7,287.44</b>

Report Ref No. CS3/ASM22009935/Ecy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.