

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22009935/Ecy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 16/11/2022 SINGAPORE 068811 ATTN: OH VALE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 9196J** SKZ 4694D Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S2M04C38 Excess (\$) 0.00 OH VALE **Assign Date** 07/10/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA ALTIS c.c Make & Model 1598 HIDDEN 2016 Engine No. Year of Reg. MR053REH104543673 **GREY** Chassis No. Colour 152270 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 205/55 R16 MICHELIN 4 mm **MICHELIN** L/H Front Tyre 205/55 R16 4 mm 205/55 R16 **MICHELIN** R/H Rear Tyre 4 mm **MICHELIN** 4 mm L/H Rear Tyre 205/55 R16 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. 5. **General Information** 30/09/2022 Inspect Date / Time 10/10/2022 (01:35 PM) Accident Date LENG YONG MOTOR WORKSHOP Survey held at 27-A JURONG PORT ROAD #01-28 JTC IND SERVICE CENTRE SINGAPORE 619101 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22009935/Ecy3e2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days