

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009939/UCY3Q2**Date:** 02/11/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00142242201

**Claimant Vehicle
No :** XD2764K**Insured
Vehicle No :** SJU1541U

Date of Loss: 05/10/2022

Nature of Claim: TP

Claim
No: SNM22D207175/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **XD2764K**

Make & Model: MITSUBISHI FP51JDR4RDEA, 12.9 D (M)

Engine No: 6M70415104

Reg. Date: 18/08/2008 (Man. Year: 2008)

Chassis No: FP51JDA00649

Colour: Blue

Odometer: 927153 km

Engine Capacity: 12882 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: ANNAITE 6 mm

Rear Left Side: HILO 6/6 mm

Front Right Side: ANNAITE 6 mm

Rear Right Side: HILO 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,043.25	10,737.47	6,305.78	37.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,710.00	1,920.00	2,790.00	59.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,753.25	12,657.47	9,095.78	41.81
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	21,753.25	9,000.00	12,753.25	58.63
+ GST 7.00/7.00% (S\$)	1,522.73	630.00	892.73	58.63
Nett Amount (S\$)	23,275.98	9,630.00	13,645.98	58.63

INSPECTION

Date of Assignment: 08/10/2022

Date Inspected: 10/10/2022 Inspected At:

Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48/50 Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Nov 2022)	
Parts:	N/A	MITSUBISHI FP51JDR4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD2764K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Repair	4,200.00 FL	*- FL
2	1		*FRONT DOOR LAMP -RH	Not Necessary	106.00 FL	*- FL
3	1		*FRONT DOOR HINGE -RH (LOWER)	Not Necessary	116.00 FL	*- FL
4	1		*FRONT CORNER PANEL -RH	Cracked	786.00 FL	*786.00 FL
5	1		*FRONT STEP PANEL INNER BRACKET RH	Twisted	276.00 FL	*276.00 FL
6	1		*FRONT STEP PANEL GARNISH -RH (TOP)	Broken	357.00 FL	*357.00 FL
7	1		*FRONT STEP PLATE (ALUMINIUM) -RH (LOWER)	Broken	298.00 FL	*298.00 FL
8	1		*FRONT STEP INNER GARNISH -RH (LOWER)	Broken	326.00 FL	*326.00 FL
9	1		*FRONT STEP OUTER GARNISH -RH (LOWER)	Broken	180.00 FL	*180.00 FL
10	1		*FRONT STEP PANEL REFLECTOR -RH	Broken	60.00 FL	*60.00 FL
11	1		*FRONT STEP PANEL LOWER GARNISH -RH	Broken	102.00 FL	*102.00 FL
12	1		*FRONT STEP PLATE SUPPORT BRACKET -RH (OUTER)	Bent	387.00 FL	*387.00 FL
13	1		*FRONT STEP PLATE SUPPORT BRACKET -RH (INNER)	Cracked	382.00 FL	*382.00 FL
14	1		*FRONT STEP GARNISH BRACKET -RH	Bent	60.00 FL	*60.00 FL
15	1		*FRONT WHEEL ARC GARNISH -RH	Distorted	420.00 FL	*420.00 FL
16	1		*FRONT WHEEL ARC RUBBER -RH	No such part	310.00 FL	*- FL
17	1		*FRONT WHEEL ARC DUST COVER -RH	Torn	264.00 FL	*264.00 FL
18	1		*FRONT WHEEL ARC DUST COVER BRACKET-RH	Bent	84.00 FL	*84.00 FL
19	1		*FRONT HEADLAMP -RH	Broken	1,100.00 FL	*1,100.00 FL
20	1		*FRONT HEADLAMP SUPPORT -RH	Cracked	489.00 FL	*489.00 FL
21	1		*FRONT HEADLAMP RIM -RH	Broken	156.00 FL	*156.00 FL
22	1		*FRONT FOG LAMP -RH	Broken	387.00 FL	*387.00 FL
23	1		*FRONT FOG LAMP RIM-RH	Broken	126.00 FL	*126.00 FL
24	1		*FRONT BUMPER	Distorted	3,950.00 FL	*2,200.83 FL
25	1		*FRONT BUMPER CORNER GARNISH -RH	Distorted	280.00 FL	*140.80 FL
26	1		*FRONT BUMPER CENTRE GARNISH -RH	Repeated	210.00 FL	*- FL
27	1		*FRONT BUMPER BRACKET -RH	Bent	198.00 FL	*198.00 FL
28	1		*FRONT CORNER PANEL LOWER RUBBER -RH	Torn	89.00 FL	*89.00 FL
29	1		*FRONT STEERING BOX (LEAKING)	Damaged	3,462.00 FL	*3,462.00 FL
30	1		*FRONT ROD LINK	Not Necessary	368.00 FL	*- FL
31	2		*FRONT HUB BEARING -RH	Not Necessary	320.00 FL	*- FL
32	1		*FRONT OIL COOLER	Bent / Twisted	896.00 FL	*896.00 FL
33	1		*FRONT OIL COOLER BRACKET -RH	Bent	150.00 FL	*150.00 FL
34	1		*FRONT OIL COOLER PIPE -RH (OUTER)	Bent	310.00 FL	*310.00 FL
35	1		*FRONT OIL COOLER PIPE -RH (INNER)	Bent	310.00 FL	*310.00 FL
36	1		*FRONT CORNER PANEL BRACKET -RH	Not Necessary	276.00 FL	*- FL
37	1		*FRONT TYRE (O/S) (LOCAL PURCHASE) (\$400.00) (60%)	Cut	480.00 FS	*240.00 FS
38	5		*LTR FRONT GEAR BOX OIL	Not Necessary	140.00 FS	*- FS
39	2		*FRONT STEERING BOX OIL	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,491.00	14,236.63
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,447.75	3,499.16
Total Parts (\$\$)	17,043.25	10,737.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	150.00	150.00
2	PANEL BEATING	New	2,800.00	1,000.00
3	CHECK WIRING	New	150.00	20.00
4	RUST PROOFING	New	80.00	0.00
5	TO REMOVE & REPLACE STEERING BOX AND WHEEL HUB BEARING }	New	350.00	150.00
6	TO REMOVE & REPLACE OIL COOLER }	New	280.00	0.00
7	TO ADJUST ALIGNMENT	New	80.00	0.00
8	TO SPRAY PAINTING	New	820.00	600.00
Gross Labour Cost (\$\$)			4,710.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >