

ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:	•			
Type of Claim :	TP	Vehicle No.	: SKQ6397X	
Typo or olding		Make & Model	: MAZDA 3	
		Year of Manufacture	: 2014	
		Chassis No.	: JM6BM42A8F0161417	
Ins Company :LE	EBERTY	Engine No.	P520248045	
Excess		Policy No.	: V	
Date of Accident : 08	.09.2022	Time of Accident	1706	
Suggested Days of Repair		In-house Vehicle Ass	essor	
Repair Estimates		Case Owner	Johari BH	
		Signature	7	
Parts (a) Cost / List Price Items	\$ 8,921.50	Contact No		
Plus/Less	-	Frt Counter Oper		
Total of Cost / List	\$ 8,921.50	63837103 – Patrick PatrickTia@sparkca		
(b) Nett Price Items	\$ -	63837730 - Brenda BrendaNg@sparkca		
		63837466 – Rohani		
Less	-	RohaniM@sparkcar	care.com	
Total of Nett Item		Workshop Opera		
(c) Special Nett Items	\$ 480.00	63837656 - Ngo Toh Wee Ngotw@sparkcarcare.com		
Total Parts Cost (Appendix A)	\$ 9,401.50	63838115 -		
		63837362 -		
Labour (Appendix B)	\$ 4,780.00			
Total Repair Cost	\$ 14,181.50			
The above total will be subjected to	to 7% G.S.T.			
Name of Surveyor				
Company				
Survey conducted on	<u></u>	at		
Remarks By Surveyor				
(a) The repair of this vehicle is	authorized / is not aut	horized until further notic	e.	
(b) Recommended Days of Re	pair :	day(s)		
(c) Resurvey	: Required / No	ot Required		
(d) Excess	:\$			
(a) Signature of our rover		D (

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	:	SKQ6397X	Case Owner	3	Johari BH
Make & Model	:	MAZDA 3	Year Manufacture	:	
Chassis No	:	JM6BM42A8F0161417	Engine No	•	P520248045
Sales Order	578		Supplier	•	
Order By	:		Type of Claim	:	<u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N	Disposit Surveyo
1	Bonnet	1	\$	560.00				Carreyo
	Bonnet rubber	1	\$	30.00				
3	Front bumper	1	\$	1,280.00				
4	Front clips	15	\$	1.50				
5	Front bumper top garnish	1	\$	351.80				
6	Front bumper reinforcement	1	\$	220.00				
7	Front grille	1	\$	610.70				
8	Front grille bracket RH	1	\$	8.00				
9	Front grille bracket Lh	1	\$	8.00				
10	Headlamp LH	1	\$	2,357.30				
11	Headlamp lower beam LH	1	\$	8.00				
12	Headlamp washer assembly LH	1	\$	120.00				
13	Headlamp washer cover LH	1	\$	50.00				
14	Front fender LH	1	\$	350.00				
15	Front fender cowling LH	1	\$	101.90				
16	Front fender cowling clip	8	\$	1.50				
1	Front fender bracket LH	1	\$	20.00				
18	Front bumper side retainer LH	1	\$	12.00				
19	Fog lamp LH	1	\$	135.00				
20	Fog lamp cover LH	1	\$	32.00				
21	Front door LH	1	\$	600.00				
22	Rear fender transparent sticker LH	1	\$	150.00				
23	LH front shock absorber	1	\$	135.00				
24	LH front knuckle arm	1	\$	230.00				
25	LH front wheel hub	1	\$	215.00				
26	LH front wheel hub lock nut	1	\$	8.00				
27	LH front tie rod	1	\$	55.00				
28	LH front tie rod end	1	\$	60.00				
29	LH front shock absorber top mounting	1	\$	45.00				
30	LH front sport rim	1	\$	1,156.80				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

<u>Labour</u>

/ehicle No. : SKQ6397X		SKQ6397X	Case Owner	:_	Johari BH	
Make & Model	:	MAZDA 3	Year of Manufacture	:	2014	

S/No 1	Labour Description	Esimated	Adjusted	
		Price	Price	
	To knock & straighten on accident area, to remove &	\$1,200.00		
	refit damage parts and realign the same.			
2	Putty and spray painting bonnet,front bumper,LH front fender,LH front	\$1,440.00		
	door,Lh rear door,LH rear fender and affected area.			
3	To check electrical lighting concerned	\$120.00		
4	To rust proof the affected area	\$280.00		
5	To transfer of door fitting,fixtureand conduct water seepage and winds noise test	\$120.00		
6	To check steering geometry and wheel alignment	\$100.00		
7	To drop front suspension undercarriage parts,remove and renewal of	\$380.00		
	the3 necessary parts,to perform final checking and testing			
8	To transfer of tire,rim and on wheel balancing	\$60.00		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.