

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22009944/APA3Q2**Date:** 17/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220034683
Claimant Vehicle No :	SNF6142L	Insured Vehicle No :	SNE7090B
Date of Loss:	07/10/2022	Nature of Claim:	TP
		Claim No:	9503138501SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF6142L	Engine No:	DNN070415
Make & Model:	AUDI Q3, 2.0 TFSI (A)	Chassis No:	WAUZZZF36N1095066
Reg. Date:	10/06/2022 (Man. Year: 2022)	Odometer:	7432 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,985.00	860.00	4,125.00	82.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,752.00	1,602.00	1,150.00	41.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,737.00	2,462.00	5,275.00	68.18
+ GST 8.00/8.00% (S\$)	618.96	196.96	422.00	68.18
Nett Amount (S\$)	8,355.96	2,658.96	5,697.00	68.18
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,110.96		

INSPECTION

Date of Assignment:	13/10/2022		
Date Inspected:	13/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,958.00 FS	*- FS
2	1		*REAR BUMPER SPOILER	Cut	510.00 FS	*408.00 FS
3	1		*REAR BUMPER TOW EYE COVER	Not Necessary	48.00 FS	*- FS
4	1		*REAR BUMPER BRACKET	Not Necessary	53.00 FS	*- FS
5	1		*REAR BUMPER REFLECTOR -RH	Not Necessary	46.00 FS	*- FS
6	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	693.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	71.00 FS	*- FS
8	1		*REAR BUMPER HOLDING STRAP -CENTER	Not Necessary	120.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR -INNER/OUTER	Not Necessary	531.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
11	2		*REAR WHEEL COVER -LH/RH	Necessary	566.00 FS	*452.00 FS
12	1		*REAR VENT TRIM	Not Necessary	79.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	4,985.00 860.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,752.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >