

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009945/UPA3Q2**Date:** 16/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210061292
Claimant Vehicle No :	PZ1473K	Insured Vehicle No :	SNA1900A
Date of Loss:	06/10/2022	Nature of Claim:	TP
		Claim No:	2400765356SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PZ1473K	Engine No:	ISF38S514189253106
Make & Model:	GOLDEN DRAGON XML6772J18, 3.8 D (M)	Chassis No:	LL3ADADE8FA002062
Reg. Date:	13/11/2015 (Man. Year: 2015)	Odometer:	387596 km
Colour:	White		
Engine Capacity:	3759 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.50	Rear Tyre Size:	215/75 R17.50 (D)
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6/6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,761.00	3,501.00	1,260.00	26.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,950.00	1,030.00	34.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,741.00	5,451.00	2,290.00	29.58
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	7,741.00	4,300.00	3,441.00	44.45
+ GST 7.00/7.00% (S\$)	541.87	301.00	240.87	44.45
Nett Amount (S\$)	8,282.87	4,601.00	3,681.87	44.45
+ Car Rental (5.0 x S\$200.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,603.00		

INSPECTION

Date of Assignment:	07/10/2022		
Date Inspected:	07/10/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BODY PANEL	Badly Dented	1,800.00 FL	*1,800.00 FL
2	1		*FRONT WINDSCREEN RUBBER	Not Necessary	600.00 FL	*- FL
3	1		*N/S HEADLAMP	Cracked	850.00 FL	*850.00 FL
4	1		*FRONT BUMPER	Dented	1,280.00 FL	*1,020.00 FL
5	1		*FRONT BUMPER FOG LAMP N/S	Cracked	280.00 FL	*220.00 FL
6	1		*FRONT CENTER GRILLE	Not Necessary	480.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,290.00	3,890.00
- List Item Discount on L Items 10.00/10.00% (\$)	529.00	389.00
Total Parts (\$)	4,761.00	3,501.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REFIT INSTRUMENT DASHBOARD ,CHECK ELECTRICAL LIGHTING AND RE-RUN ,RE-ROUTE WIRE HARNESS	New	400.00	200.00
2	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	180.00	100.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	30.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	150.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ADJUST AND REALIGN THE SAME	New	1,200.00	1,000.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	900.00	600.00
Gross Labour Cost (\$\$)			2,980.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >