

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22009951/DYA3Q2**Date:** 18/07/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414_03

Claimant Vehicle No : SLT5335D **Insured Vehicle No :** SNA5355Y

Date of Loss: 21/09/2022 Nature of Claim: TP Claim No: MFL2022D0005358

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT5335D**
 Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Engine No: LEB5961916
 Reg. Date: 31/10/2017 (Man. Year: 2017) Chassis No: RU31261899
 Colour: Silver Odometer: 454580 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: KAPSEN 5 mm Rear Left Side: KAPSEN 5 mm
 Front Right Side: KAPSEN 5 mm Rear Right Side: KAPSEN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,536.38	4,566.60	15,969.78	77.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	1,360.00	4,090.00	75.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,986.38	5,926.60	20,059.78	77.19
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	25,986.38	3,850.00	22,136.38	85.18
+ GST 8.00/8.00% (S\$)	2,078.91	308.00	1,770.91	85.18
Nett Amount (S\$)	28,065.29	4,158.00	23,907.29	85.18
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
(S\$)		4,578.00		
Liabe Amount (95.00%) (S\$)		4,349.10		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		4,380.10		
Global Sum Settlement (S\$)		4,200.00		

INSPECTION

Date of Assignment: 10/10/2022

Date Inspected: 11/10/2022 Inspected At:

C. S. Ong Auto Pte Ltd (HQ)
 BLOCK 10 ANG MO KIO IND PK 2A
 #02-16 AMK AUTOPOINT
 SINGAPORE 568047

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT5335D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,492.30 F	*- FL
2	1		*BONNET LOCK	Not Necessary	98.50 F	*- FL
3	1		*BONNET STRIKER LOCK	Not Necessary	49.20 F	*- FL
4	1		*BONNET INSULATOR	Not Necessary	122.30 F	*- FL
5	2		*BONNET HINGE	Not Necessary	97.00 F	*- FL
6	1		*HEAD LAMP RH	Mtg Cracked	3,820.00 F	*1,850.00 FL
7	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	98.00 F	*- FL
8	1		*HEAD LAMP WIRE HARNESS	Not Necessary	980.00 F	*- FL
9	1		*FRONT BUMPER	Distorted/Mtg Cracked	801.70 F	*765.00 FL
10	2		*FRONT BUMPER SIDE RETAINER LH / RH	Serviceable	27.50 F	*- FL
11	1		*FRONT BUMPER LOWER	Cut/Distorted	491.00 F	*355.00 FL
12	1		*FRONT BUMPER FOG LED LAMP RH	Not Necessary	510.00 F	*- FL
13	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	48.00 F	*- FL
14	1		*FRONT BUMPER FOG LAMP HOLDER RH	Not Necessary	35.00 F	*- FL
15	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	980.00 F	*- FL
16	1		*FRONT FENDER RH	Dented	780.30 F	*580.00 FL
17	1		*FRONT FENDER ARC GARNISH RH	Cut	392.00 F	*201.70 FL
18	1		*FRONT FENDER HYBRID EMBLEM	Necessary	112.00 F	*65.50 FL
19	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	142.30 F	*- FL
20	1		*FRONT WHEEL BEARING & HUB ASSY RH	Damaged	338.30 F	*262.00 FL
21	1		*FRONT KNUCKLE ARM RH	Distorted	430.10 F	*375.00 FL
22	1		*FRONT SHOCK ABSORBER RH	Distorted	520.19 F	*373.40 FL
23	1		*FRONT LOWER ARM RH	Distorted	485.00 F	*336.90 FL
24	1		*FRONT DOOR RH	Repair	1,830.50 F	*- FL
25	1		*FRONT DOOR INNER LOCK	Not Necessary	217.40 F	*- FL
26	1		*FRONT DOOR WINDOW GLASS MOULDING RH	Not Necessary	978.20 F	*- FL
27	1		*FRONT DOOR PILLAR BLACK STICKER RH	Not Necessary	98.20 F	*- FL
28	1		*FRONT DOOR WEATHER STRIP INNER RH	Not Necessary	384.59 F	*- FL
29	2		*FRONT DOOR HINGE	Not Necessary	204.80 F	*- FL
30	1		*FRONT DOOR CHECKER RH	Not Necessary	112.00 F	*- FL
31	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	300.00 FS	*- FS
32	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*FRONT GRILLE CLIPS	Not Necessary	1,500.00 FS	*- FS
34	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
37	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*COOLANT	Not Necessary	100.00 FS	*- FS
40	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
41	1		*FRONT FENDER ARC GARNISH CLIPS	Necessary	80.00 FS	*15.00 FS
42	1		*FRONT TYRE RH	Serviceable	300.00 FS	*- FS
43	1		*FRONT RIM RH	Cut	1,200.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	20,536.38	5,599.50
	- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,032.90

Report was unsubmitted during this print-out.

7/18/23, 3:09 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	20,536.38
						4,566.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	600.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	500.00
3	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	150.00
4	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
5	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	150.00	60.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNIT. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
8	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	New	200.00	20.00
Gross Labour Cost (\$\$)			5,450.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >