

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5248P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (DISC 25%)	BUCKLED	478.90	359.18
10	BUMPER CLIPS @\$2.40 (DISC 25%)	NECESSARY	24.00	18.00
1	BUMPER LIP COVER RR/LH (DISC 25%)	DISTORTED	93.90	70.43
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	234.70	-
1	ARM SUB-ASSY ,RR BUMPER RH	NOT NECESSARY	157.90	-
1	ARM SUB-ASSY ,RR BUMPER LH	NOT NECESSARY	157.90	-
1	ARM SUB-ASSY ,RR BUMPER LH	NOT NECESSARY	157.90	-
1	ANTENNA ,ELECTRICAL LOWER REAR	NOT NECESSARY	208.10	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER SEAL ,RR LH	NOT NECESSARY	101.80	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	155.40	-
1	UNDER COVER SUB-ASSY ,RR FLOOR	NOT NECESSARY	586.10	-
1	UNDER COVER RR SHIELD	NOT NECESSARY	66.10	-
1	END PANEL	NOT NECESSARY	755.10	-
1	TAIL LAMP BRACKET ,LH	NOT NECESSARY	35.20	-
1	TAIL LAMP LH	NOT NECESSARY	618.60	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	108.70	-
1	BUMPER LIP REAR	SERVICEABLE	301.90	-
			4,422.20	447.61
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK .		676.00	200.00
	SPRAY PAINT.		738.00	200.00
	TOWING CHARGE.	NOT NECESSARY	56.00	-
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION .	NOT NECESSARY	120.00	-
	TO APPLY RUST -PROOFING ON AFFECTED AREA .	NOT NECESSARY	100.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	50.00
	TO REPLACE SUNDRY PARTS .	NOT NECESSARY	100.00	-
			1,970.00	450.00
	GRAND TOTAL		6,392.20	897.61

Report Ref No. CS/SMO22009952/Kvy3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO22009952/Kvy3q2

KONG SENG CHEONG

Licensed Appraiser