



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 4150T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	980.00	980.00
1	RH REAR BUMPER SIDE RETAINER	DAMAGED	32.00	32.00
1	RH REAR BUMPER REFLECTOR	CRACKED	86.00	86.00
1	REAR BUMPER DIFFUSER	DEFORMED	265.00	265.00
2	REAR BUMPER REVERSE SENSOR @\$140.00	DAMAGED (1PC ONLY)	280.00	140.00
1	RH REAR TAILLAMP	CUT	380.00	380.00
1	RH REAR TAILLAMP LOWER BRACKET	CRACKED	48.00	48.00
1	RH REAR FENDER	TO REPAIR SEE LABOUR	1,340.00	-
1	RH REAR FENDER AIR VENT	NOT NECESSARY	78.00	-
1	RH REAR FENDER INNER COWLING	NOT NECESSARY	143.00	-
1	REAR TAILGATE	CRACKED	1,560.00	1,560.00
1	REAR TAILGATE LOWER GARNISH	DEFORMED	345.00	345.00
1	REAR TAILGATE EMBLEM LOGO	NECESSARY	78.00	78.00
1	REAR TAILGATE EMBLEM CITROEN	NECESSARY	82.00	82.00
1	REAR TAILGATE EMBLEM PICASSO	NECESSARY	90.00	90.00
1	REAR AXLE	NOT NECESSARY	2,250.00	-
1	RH REAR SHOCK ABSORBER	DAMAGED	245.00	245.00
1	RH REAR WHEEL BEARING	DAMAGED	186.00	186.00
1	REAR BUMPER REINFORCEMENT	DENTED	565.00	565.00
1	REAR BUMPER REINFORCEMENT COVER	DEFORMED	125.00	125.00
1	REAR BUMPER CHROME	NECESSARY	165.00	165.00
	LESS 10% DISCOUNT		-932.30	-537.20
			8,390.70	4,834.80
<u>SPECIAL NETT ITEMS</u>				
1	RH REAR SPORT RIM (SN)	CUT	850.00	650.00
4	RH REAR TYRE (SN)	NOT NECESSARY	320.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
2	RH REAR FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
			1,290.00	680.00

Report Ref No. CS/AGI22009956/Avy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR FOR PANEL BEATING. INCLUSIVE OF THE REPAIR OF RH REAR FENDER.		1,800.00	600.00
	LABOUR FOR SPRAY PAINTING.		1,400.00	800.00
	WIRING CHECK.		80.00	30.00
	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS.		300.00	60.00
	LABOUR REMOVE & TRANSFER ALL REAR TAILGATE FITTING.		250.00	80.00
	LABOUR FOR REMOVE & RENEW BOTH REAR WINDSCREEN GLASS.		150.00	120.00
	LABOUR FOR REMOVE AND REFIT UNDERCARRIAGE.		350.00	180.00
			4,330.00	1,870.00
	GRAND TOTAL		14,010.70	7,384.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,900.00

Report Ref No. CS/AGI22009956/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.