

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III22009958/SVY3E2  
**Date:** 07/11/2022

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372_01
<b>Claimant Vehicle No :</b>	SLW4210X	<b>Insured Vehicle No :</b>	SHD2487A
Date of Loss:	07/10/2022	Nature of Claim:	TP
			Claim No: MFL2022D0005773

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLW4210X</b>		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)	Engine No:	G4FGJU133898
Reg. Date:	12/02/2018 (Man. Year: 2018)	Chassis No:	KMHD841CMJU627148
Colour:	Red	Odometer:	99172 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	10/10/2022		
Date Inspected:	18/10/2022	Inspected At:	Zolar Auto (HQ) 1 Kaki Bukit Ave 6, #02-42 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	0.0 days		

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 03 Nov 2022)

**Parts:**            143            HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**          Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLW4210X)

**Validity:**        These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**