

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 2016E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (CONSISTENT)	TO REPAIR SEE LABOUR	1,024.00	-
1	BOOTLID EMBEM 'ALTIS'(CONSISTENT)	NECESSARY	65.00	65.00
1	BOOTLID SENSOR (CONSISTENT)	NOT NECESSARY	312.00	-
1	BOOTLID EMBELM 'COROLLA'(CONSISTENT)	NECESSARY	65.00	65.00
1	REAR BUMPER (CONSISTENT)	DEFORMED	698.00	542.00
2	REAR BUMPER SIDE RETAINER @\$112.00(CONSISTENT)	NOT NECESSARY	224.00	-
2	REAR BUMPER BRACKET @\$168.00(CONSISTENT)	NOT NECESSARY	326.00	-
2	REAR BUMPER SENSOR @\$381.00(CONSISTENT)	NOT NECESSARY	762.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	395.00	332.70
2	REAR BUMPER REFLECTOR @\$112.00(CONSISTENT)	NOT NECESSARY	224.00	-
	LESS 25% DISCOUNT		-1,023.75	-251.18
			3,071.25	753.52
	SPECIAL NETT ITEMS			
1	BOOTLID INSULATOR CLIPS (SN)(CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	40.00	30.00
			70.00	30.00
	<u>LABOUR</u>			
	SPRAY PAINTING ON AFFECTED AREAS .		500.00	400.00
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF BOOTLID .		500.00	300.00
	TO CHECK ELECTRICAL WIRING.		100.00	40.00
	APPLY ANTI RUST ON AFFECTED AREAS .	NOT NECESSARY	50.00	
			1,150.00	740.00
	GRAND TOTAL		4,291.25	1,523.52

Report Ref No. CC4/ASM22009959/Rpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM22009959/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

monto

HO LEONG CHUAN

Automotive Assessor