

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009971/EQY3M4**Date:** 21/10/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00204972101

Claimant Vehicle No : SGP6407D **Insured Vehicle No :** SJW8972C

Date of Loss: 03/09/2022 Nature of Claim: TP Claim No: SNM22D206335/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGP6407D**

Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1722539

Reg. Date: 21/12/2006 (Man. Year: 2006) Chassis No: RN61019603

Colour: Silver Odometer: 609419 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm

Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,539.97	51.82	1,488.15	96.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	760.00	1,170.00	60.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,469.97	811.82	2,658.15	76.60
+ GST 7.00/7.00% (\$\$)	242.90	56.83	186.07	76.60
Nett Amount (\$\$)	3,712.87	868.65	2,844.22	76.60

INSPECTION

Date of Assignment: 10/10/2022

Date Inspected: 13/10/2022 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

Different 1 cents -Finalise confirm amount: \$811.83

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2022)
Parts:	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGP6407D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair (Dismantle and verify)	731.90 FL	*- FL
2	1		*FRT BUMPER RETAINER RH	Broken	30.10 FL	*30.10 FL
3	10		*FRT BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
4	1		*FRT FENDER RH	Repair	570.40 FL	*- FL
5	1		*FRT DOOR GLASS OUTER MOULDING R	Not Necessary	95.40 FL	*- FL
6	1		*FRT SIDE MIRROR ASSY RH	Not Necessary	586.50 FL	*- FL
					Sub Total (S\$)	2,053.30 69.10
					- List Item Discount on L Items 25.00/25.00% (S\$)	513.33 17.28
					Total Parts (S\$)	1,539.97 51.82

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK FRT DOOR RH,RR DOOR RH,RR FENDER RH ,WELD	New	800.00	300.00
2	REMOVE & REPLACE ABOVE PARTS (NPA)	New	0.00	0.00
3	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	400.00
4	TO CHECK WIRING	New	30.00	30.00
5	TO APPLY ANTI RUST COATING	New	100.00	30.00
Gross Labour Cost (\$)			1,930.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >