

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

QA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMF 4356L Yr Regt: 12/11/18  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Private Motor /  
 Truck / Trailer or  
 Make: Mitsubishi Attrage No. 1193  
 Colour: Red A/O: Insured / Std / NI / NA  
 Sp. Reading: 26017 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 CNo: MMRSTIA/BAJH003896  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / STD A/Rim or  
 Tyre Size: F: 185/55R15  
 R: 17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTO / PIR / SUMI  
 TOYO / YOKO or \_\_\_\_\_  
 Front  
 R/Bal. 4 mm  
 L/Bal. 4 mm  
 D.O.A. 2/10/22  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Fnt / Rear / O/S / N/S / U/S / Rooktop of  
 The UIC / Chassis frame / Body Structure affected due to collision.

Rear  
 R/Bal. 4 mm  
 L/Bal. 4 mm  
 D.O.A. 15/11/22

Date/Time Action/Instruction

MY-60K

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / L.B.L. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation

LS + RS (\$)

Notes

Others

TOTAL



**Main Office :** No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 6891

**Service Centre :** Block 100B, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (B Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0008864-2

**Mova Spray Centre**  
2K Oven Spray Painting System

**Power-M Automotive Pte Ltd**  
Specialise in Car Air-con Services,  
Car Audio & Hi-Fi System.

**Hilton Car Rental Centre**  
Hilton Auto Trading  
Dealing in New/Used Cars, Hire Purchase & Insurance.



**TP INSURER:**  
**UNKNOWN**

**Allianz Insurance Singapore Pte. Ltd. (HQ)**

Singapore

#### PARTICULARS OF CLAIM

|                               |                                       |                    |                   |
|-------------------------------|---------------------------------------|--------------------|-------------------|
| Claim Type:                   | THIRD PARTY                           | Ref. No:           |                   |
| Policy No:                    |                                       | Date of Loss:      | 02/10/2022        |
| Vehicle Reg. No.:             | SMF4356L                              | Driveable?         |                   |
| Party At Fault:               | UNKNOWN                               |                    |                   |
| Make/Model:                   | MITSUBISHI ATTRAGE, 1.2 (A)           | Vehicle Reg. Date: | 12/11/2018        |
| Vehicle Colour:               | RED                                   | Chassis No:        | MMBSTA13AJH003896 |
| Engine No:                    | 3A92UHH8238                           |                    |                   |
| Odometer:                     | 0 KM                                  |                    |                   |
| Paint Type:                   |                                       |                    |                   |
| Total Loss?                   | NO                                    |                    |                   |
| Est. Duration of Repair (day) | 10                                    |                    |                   |
| Present Location:             | MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) |                    |                   |

| COST OF CLAIMS           | Amount          |
|--------------------------|-----------------|
| Parts                    | 4,730.00        |
| Miscellaneous Items      | 690.00          |
| Labour                   | 1,870.00        |
| Paintwork Labour         | 0.00            |
| Towing                   | 0.00            |
| <b>Gross Total (S\$)</b> | <b>7,290.00</b> |
| <b>+ GST 7.00% (S\$)</b> | <b>510.30</b>   |
| <b>Nett Amount (S\$)</b> | <b>7,800.30</b> |

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Oct 2022)  
 Parts: 143 MITSUBISHI ATTRAGE 1.2 (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SMF4356L)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                     | %Disc | %Depr | Amount      |
|-----|-----|----------|---------------------------------|-------|-------|-------------|
| 1   | 1   |          | *REAR BOOT / DO                 | 0.00  | 0.00  | *490.00 F   |
| 2   | 1   |          | *REAR BOOT LOGO - MK            | 0.00  | 0.00  | *40.00 F    |
| 3   | 1   |          | *REAR BOOT EMBLEM ATTRAGE - MK  | 0.00  | 0.00  | *45.00 F    |
| 4   | 1   |          | *REAR BOOT EMBLEM MIVEC - MK    | 0.00  | 0.00  | *45.00 F    |
| 5   | 1   |          | *REAR BOOT EMBLEM C&C - MK      | 0.00  | 0.00  | *40.00 F    |
| 6   | 1   |          | *REAR BOOT CHROME - MK          | 0.00  | 0.00  | *290.00 F   |
| 7   | 1   |          | *REAR BOOT LOCK                 | 0.00  | 0.00  | *155.00 F   |
| 8   | 1   |          | *REAR BOOT RUBBER X             | 0.00  | 0.00  | *125.00 F   |
| 9   | 1   |          | *REAR BOOT CATCH X              | 0.00  | 0.00  | *20.00 F    |
| 10  | 1   |          | *REAR LAMP RH - BR              | 0.00  | 0.00  | *205.00 F   |
| 11  | 3   |          | *REAR LAMP GROMMET RH X         | 0.00  | 0.00  | *12.00 F    |
| 12  | 1   |          | *REAR LAMP PANEL RH X           | 0.00  | 0.00  | *40.00 F    |
| 13  | 1   |          | *REAR END PANEL                 | 0.00  | 0.00  | *300.00 F   |
| 14  | 1   |          | *REAR END PANEL TRIM            | 0.00  | 0.00  | *75.00 F    |
| 15  | 6   |          | *REAR END PANEL TRIM CLIPS      | 0.00  | 0.00  | *18.00 F    |
| 16  | 1   |          | *REAR BUMPER - DO               | 0.00  | 0.00  | *395.00 F   |
| 17  | 1   |          | *REAR BUMPER LOWER SPOILER - BR | 0.00  | 0.00  | *1,600.00 F |
| 18  | 2   |          | *REAR BUMPER RETAINER L+R - BR  | 0.00  | 0.00  | *70.00 F    |
| 19  | 1   |          | *REAR BUMPER SIDE SHIELD RH X   | 0.00  | 0.00  | *35.00 F    |
| 20  | 10  |          | *REAR BUMPER CLIPS - MK         | 0.00  | 0.00  | *30.00 F    |
| 21  | 1   |          | *REAR KEYLESS SENSOR            | 0.00  | 0.00  | *160.00 F   |
| 22  | 1   |          | *REAR BUZZER                    | 0.00  | 0.00  | *110.00 F   |

F=Franchise part.

Sub Total (\$\$) 4,300.00  
 + Margin on L,N Items 10.00% (\$\$) 430.00  
 Total Parts (\$\$) 4,730.00

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars                      | Amount |
|----------------------------|-----|----------------------------------|--------|
| <u>Miscellaneous Items</u> |     |                                  |        |
| 1                          | 1   | REAR BOOT TOP GARNISH <i>X R</i> | 450.00 |
| 2                          | 1   | REAR BUMPER SENSOR <i>Shu!</i>   | 200.00 |
| 3                          | 1   | REAR NUMBER PLATE <i>X</i>       | 40.00  |
| Sub Total (S\$)            |     |                                  | 690.00 |

## Estimates on Labour

| No                      | Particulars                                                                                                                                                                             | Lab.Type       | Amount   |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------|
| <u>Labour Items</u>     |                                                                                                                                                                                         |                |          |
| 1                       | TO CUT & WELD REAR END PANEL, TAILLAMP PANEL RH, TO REPAIR REAR FENDER L+R, SPARE TYRE PANEL, REAR CHASSIS MEMBER. TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS | New <i>600</i> | 840.00   |
| 2                       | TO SPRAY AFFECTED AREAS                                                                                                                                                                 | New <i>800</i> | 850.00   |
| 3                       | TO REMOVE & REFIX LUGGAGE COMPARTMENT, SIDE GARNISH, SIDE TRIM BOARD, CARPET & OTHER ATTACHMENT PARTS                                                                                   | New <i>50</i>  | 80.00    |
| 4                       | TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE                                                                                                                                         | New <i>30</i>  | 60.00    |
| 5                       | TO RUST PROOF AFFECTED AREAS                                                                                                                                                            | New <i>30</i>  | 40.00    |
| Gross Labour Cost (S\$) |                                                                                                                                                                                         |                | 1,870.00 |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)

13/11/22, 11:00am

*m n*

*R L/S*

*M AL G*

*5 d/s*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: