

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIS22009975/EPA3Q2**Date:** 20/12/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001037805
Claimant Vehicle No :	SMF2849U	Insured Vehicle No :	XE4126J
Date of Loss:	07/10/2022	Nature of Claim:	TP
		Claim No:	202222007307KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF2849U		
Make & Model:	VOLKSWAGEN TOURAN, 1.4 1.4 TSI CL 5T13NZ (A)	Engine No:	CZD175706
Reg. Date:	31/10/2018 (Man. Year: 2018)	Chassis No:	WVGZZZ1TZKW005718
Colour:	Gold	Odometer:	25936 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,406.50	8,675.86	1,730.64	16.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,280.00	6,720.00	4,560.00	40.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	21,686.50	15,395.86	6,290.64	29.01
+ GST 7.00/7.00% (\$\$)	1,518.06	1,077.71	440.35	29.01
Nett Amount (\$\$)	23,204.56	16,473.57	6,730.99	29.01
+ Loss of Use (13.0 x S\$60.00/day) (\$\$)		780.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		17,255.57		

INSPECTION

Date of Assignment:	10/10/2022		
Date Inspected:	10/10/2022	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	9.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2022)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.4 1.4 TSI CL 5T13NZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF2849U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*1K WINDOW ADHESIVE (2 PCS)	Necessary	92.59 FS	*92.59 FS
2	1	*ALL PURPOSE CLEANER	Necessary	92.59 FS	*92.59 FS
3	1	*PRIMER	Necessary	27.24 FS	*27.24 FS
4	1	*ACTIVATOR	Necessary	23.64 FS	*23.64 FS
5	1	*APPLICATOR (2 PCS)	Necessary	20.09 FS	*20.09 FS
6	1	*REAR TRUNK LID	Dented	2,509.89 FS	*2,509.89 FS
7	1	*SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM LH	Necessary	273.89 FS	*273.89 FS
8	1	*SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM RH	Necessary	278.70 FS	*278.70 FS
9	1	*PACKING ADHESIVE RR NUMBER PLATE PACKING	Necessary	29.62 FS	*29.62 FS
10	1	*RIVETTED CAP NUT (4 PCS)	Necessary	9.50 FS	*9.50 FS
11	1	*HOOD LATCH BOOT LID LOCK	Not Necessary	173.66 FS	*- FS
12	1	*COVER LOCK SATIN BLACK LOCK COVER	Cut	14.53 FS	*14.53 FS
13	1	*PUSHBUTTON FOR ELECTRIC L BOOT OPENED PUSH BUTTON	Broken	1,368.68 FS	*1,368.68 FS
14	1	*GASKET BOOT WEATHERSTRIP	Torn	312.05 FS	*312.05 FS
15	1	*WIPER MOTOR	Not Necessary	382.46 FS	*- FS
16	1	*VW SIGN BLACK /BRIGHT CHRO	Broken	105.35 FS	*105.35 FS
17	1	*INSCRIPTION BRIGHT CHROME NAME PLATE -TOURAN	Necessary	72.33 FS	*72.33 FS
18	1	*ADDITIONAL BRAKE LIGHT WI 3RD BRALELIGHT	Necessary	221.24 FS	*221.24 FS
19	1	*TAILLIGHT WITH BACK-UP LI TAILLIGHT INNER LH	Broken	258.57 FS	*258.57 FS
20	1	*TAILLIGHT WITH BACK-UP LI TAILLIGHT INNER RH	Broken	258.57 FS	*258.57 FS
21	1	*TAILLIGHT TAILLIGHT OUTER LH	Cut	310.15 FS	*310.15 FS
22	1	*TAILLIGHT TAILLIGHT OUTER RH	Broken	310.15 FS	*310.15 FS
23	1	*TRIM PANEL FOR HATCH GATE BOOT LID TRIM COVER	Crushed	271.88 FS	*271.88 FS
24	1	*COVER FOR BUMPER PRIMED	Broken	1,383.43 FS	*1,383.43 FS
25	1	*SPOILER SATIN BLACK	Not Necessary	331.91 FS	*- FS
26	1	*BUMPER REINFORCEMENT	Not Necessary	614.14 FS	*- FS
27	1	*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	65.59 FS	*- FS
28	1	*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	44.89 FS	*- FS
29	1	*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	44.89 FS	*- FS
30	1	*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	36.55 FS	*- FS
31	1	*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	36.55 FS	*- FS
32	1	*REFLECTOR RHS REFLECTOR OUTER	Broken	68.21 FS	*68.21 FS
33	1	*REFLECTOR RHS REFLECTOR INNER	Broken	68.21 FS	*68.21 FS
34	1	*STONE PROTECTION FOIL LHR FENDER FOIL	Necessary	32.38 FS	*32.38 FS
35	1	*STONE PROTECTION FOIL RHR FENDER FOIL	Necessary	32.38 FS	*32.38 FS
36	1	*REAR WATER LEAK TEST	Necessary	150.00 FS	*150.00 FS
37	1	*REAR NAMBER PLATE	Cut	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 10,406.50 8,675.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	4,320.00	2,160.00
2	SPRAY PAINT	New	4,760.00	2,720.00
3	R&R REAR W/SCREEN	New	720.00	720.00
4	TRANSFER BOOT LID MECHANISM	New	720.00	360.00
5	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
6	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
Gross Labour Cost (S\$)			11,280.00	6,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >