

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009976/AVY3Q2**Date:** 23/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00002032200

Claimant Vehicle No : SMU3340J **Insured Vehicle No :** SND7658U

Date of Loss: 10/10/2022 Nature of Claim: TP Claim No: SNM22D207234/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU3340J**

Make & Model: HONDA JAZZ, 1.3 (A) Engine No: L13B15000845

Reg. Date: 07/08/2020 (Man. Year: 2020) Chassis No: JHMGK3850LS218070

Colour: White Odometer: 44146 km

Engine Capacity: 1318 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,937.36	3,127.28	2,810.08	47.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,970.00	1,520.00	43.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,427.36	5,097.28	4,330.08	45.93
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	9,427.36	4,000.00	5,427.36	57.57
+ GST 7.00/7.00% (S\$)	659.92	280.00	379.92	57.57
Nett Amount (S\$)	10,087.28	4,280.00	5,807.28	57.57

INSPECTION

Date of Assignment: 22/12/2022

Date Inspected: 10/10/2022 Inspected At: 23 KAKI BUKIT AVENUE 4
#02-03A AAS KAKI BUKIT CENTRE
SINGAPORE 415933
Repairer: Chia Auto Services Pte Ltd (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts: 144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMU3340J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,122.00 FL	*843.00 FL
2	1		*TAIL GATE LOGO	Not Necessary	58.00 FL	*- FL
3	1		*TAIL GATE EMBLEM FIT	Necessary	58.00 FL	*58.00 FL
4	1		*TAIL GATE LOGO EMBLEM	Not Necessary	210.00 FL	*- FL
5	1		*TAIL GATE DETECTOR	Not Necessary	155.30 FL	*- FL
6	1		*TAIL GATE BUZZEL	Not Necessary	180.00 FL	*- FL
7	1		*TAIL GATE INNER LOCK	Damaged	225.80 FL	*158.00 FL
8	1		*TAIL GATE INNER HANDLE	Not Necessary	90.00 FL	*- FL
9	1		*TAIL GATE WEATHERSTRIP	Not Necessary	128.00 FL	*- FL
10	1		*TAIL GATE INNER TRIM	Cracked	230.00 FL	*230.00 FL
11	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	155.30 FL	*155.30 FL
12	1		*REAR BUMPER	Deformed	730.00 FL	*529.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	84.00 FL	*84.00 FL
14	1		*REAR BUMPER CENTRE GARNISH	Cracked	230.80 FL	*230.80 FL
15	2		*REAR BUMPER SIDE GARNISH	Cracked	241.00 FL	*241.00 FL
16	1		*TAIL LAMP	N/S Cracked	840.00 FL	*295.00 FL
17	2		*TAIL LAMP PANEL	Not Necessary	420.00 FL	*- FL
18	2		*REAR FENDER INNER TRIM	Not Necessary	841.00 FL	*- FL
19	1		*REAR END PANEL	Dented	520.00 FL	*420.00 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	190.00 FL	*190.00 FL
21	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
22	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS
23	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
25	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	20.00 FS	*- FS
26	1		*SET TAIL LAMP CLIP	Necessary	20.00 FS	*10.00 FS
27	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
28	1		*REAR END PANEL INSULATION SEALANT	Necessary	120.00 FS	*60.00 FS
29	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,279.20	3,814.10
- List Item Discount on L Items 20.00/20.00% (\$)	1,341.84	686.82
Total Parts (\$)	5,937.36	3,127.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
8	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
Gross Labour Cost (S\$)			3,490.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >