

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22009981/UVY3Q2**Date:** 26/10/2022REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG22008633
Claimant Vehicle No :	SLA9610H	Insured Vehicle No :	YQ4255U
Date of Loss:	07/10/2022	Nature of Claim:	TP
		Claim No:	CDMCG22002123

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA9610H	Engine No:	27195231003308
Make & Model:	ADIVA AD1 200, 190cc 3W	Chassis No:	WDD2040462A100361
Reg. Date:	29/02/2008 (Man. Year: 2007)	Odometer:	185764 km
Colour:	Grey		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,468.95	3,709.24	4,759.71	56.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	420.00	1,640.00	79.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,528.95	4,129.24	6,399.71	60.78
Approved Total (Overridden) (\$\$)		3,300.00		
(\$\$)	10,528.95	3,300.00	7,228.95	68.66
+ GST 7.00/7.00% (\$\$)	737.03	231.00	506.03	68.66
Nett Amount (\$\$)	11,265.98	3,531.00	7,734.98	68.66

INSPECTION

Date of Assignment:	10/10/2022	
Date Inspected:	17/10/2022	Inspected At: Convergence Automotive Pte Ltd (HQ) 39 Woodlands Close, MEGA@Woodlands #01-24 Singapore 737856
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Oct 2022)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA9610H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	1,650.50 FL	*1,466.32 FL
2	1		*FRONT BUMPER INNER FRAME	Not Necessary	199.00 FL	*- FL
3	1		*FRONT BUMPER LOWER CHROME MOULDING	Necessary	185.00 FL	*185.00 FL
4	1		*FRONT BUMPER SIDE GRILLE (O/S)	Twisted	142.00 FL	*142.00 FL
5	1		*FRONT BUMPER INNER SPONGE	Not Necessary	155.00 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	182.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	522.00 FL	*- FL
8	2		*FRONT BUMPER REINFORCEMENT STAY BRACKETS	Not Necessary	554.00 FL	*- FL
9	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	151.00 FL	*- FL
10	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	50.00 FL	*- FL
11	1		*FRONT FENDER (RH)	Not Necessary	985.00 FL	*- FL
12	1		*FRONT FENDER INNER SHIELD (RH)	Not Necessary	185.00 FL	*- FL
13	1		*FRONT HEADLAMP (RH)	Cracked	2,617.00 FL	*2,272.50 FL
14	1		*FRONT HEADLAMP PANEL (RH)	Not Necessary	188.00 FL	*- FL
15	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
16	1		*SET FRONT BUMPER CLIPS	Necessary	65.00 FS	*50.00 FS
17	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	55.00 FS	*- FS
18	1		*FRONT ALLOY RIM (RH)	Not Necessary	800.00 FS	*- FS
19	1		*FRONT TYRE (RH)	Not Necessary	500.00 FS	*- FS
					Sub Total (\$\$)	9,245.50 4,115.82
					- List Item Discount on L Items 10.00/10.00% (\$\$)	776.55 406.58
					Total Parts (\$\$)	8,468.95 3,709.24

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET HEADLAMP FOCUSING }	New	80.00	20.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT }	New	80.00	0.00
3	TO APPLY UNDERCOATING & RUST PROOFING	New	100.00	0.00
4	PANEL BEATING	New	1,000.00	200.00
5	SPRAY PAINTING	New	800.00	200.00
Gross Labour Cost (\$\$)			2,060.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >