



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 6326Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	OS TAIL LAMP	BROKEN	949.12	949.12
1	OSR BUMPER (CITARO)	BROKEN	746.18	746.18
1	FOGLIGHT (LAMP)	BROKEN	60.22	60.22
1	SIDE MARKER LIGHT	CUT	74.60	74.60
1	DOWEL (ANCHOR)	NECESSARY	4.40	4.40
	LESS 10% DISCOUNT		-	-183.45
			1,834.52	1,651.07
<b>LABOUR</b>				
	TO DISMANTLE & REPLACE : - ITEM NOS 1 - 5.		1,950.00	650.00
	TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS : - RADIATOR FLAP ACCESS DOOR	NOT NECESSARY	975.00	-
	SPRAY PAINTING : - RADIATOR FLAP ACCESS DOOR - OSR CORNER BUMPER		1,280.00	1,280.00
			4,205.00	1,930.00
<b>GRAND TOTAL</b>			<b>6,039.52</b>	<b>3,581.07</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,581.07</b>

Report Ref No. CS/SMR22009983/Eqy3m4

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.