

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 828Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / DEFORMED	745.00	745.00
1	SET REAR BUMPER CLIP	NECESSARY	65.00	50.00
1	REAR BUMPER REINFORCEMENT	BENT	475.30	475.30
1	REAR BUMPER BRACKET RH	NOT NECESSARY	258.10	-
1	REAR BUMPER REFLECTOR RH	CRACKED	117.60	117.60
1	REAR TAILGATE "PROFESSIONAL" EMBLEM	NOT NECESSARY	163.50	-
1	REAR TAILGATE "DOBLO" EMBLEM	NOT NECESSARY	105.00	-
1	REAR TAILGATE "MAXI" EMBLEM	NOT NECESSARY	90.00	-
1	REAR TAILGATE "MULTIJET" EMBLEM	NOT NECESSARY	92.00	-
1	REAR TAILGATE "90" EMBLEM	NOT NECESSARY	97.50	-
	LESS 10% DISCOUNT		-	-138.79
			2,209.00	1,249.11
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	220.00	200.00
1	REAR TAILGATE "6 PAX" STICKER (SN)	NOT NECESSARY	15.00	-
1	REAR TAILGATE "70 KM/H" STICKER (SN)	NOT NECESSARY	15.00	-
			250.00	200.00
	<u>LABOUR</u>			
	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR.		120.00	50.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNTION.		50.00	20.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS.		600.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		600.00	480.00
	TO APPLY RUST PROOFING , RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.	NOT NECESSARY	80.00	-
			1,450.00	850.00
	GRAND TOTAL		3,909.00	2,299.11

Report Ref No. CS/SMR22009989/Uvy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR22009989/Uvy3m4

CHUA KANG SENG
Licensed Appraiser