

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22009998/UPA3Q2
Date: 19/12/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100503613
Claimant Vehicle No : CB7828L **Insured Vehicle No :** SLL8314L
Date of Loss: 11/10/2022 Nature of Claim: TP Claim No: 5573192918SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **CB7828L**
Make & Model: TOYOTA HIACE, 3.0 COMMUTER GL (A) Engine No: 1KD2649574
Reg. Date: 25/11/2016 (Man. Year: 2016) Chassis No: KDH2230029602
Colour: Silver Odometer: 271168 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,696.22	2,106.22	590.00	21.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	1,520.00	1,340.00	46.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,556.22	3,626.22	1,930.00	34.74
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	5,556.22	2,900.00	2,656.22	47.81
+ GST 7.00/7.00% (S\$)	388.94	203.00	185.94	47.81
Nett Amount (S\$)	5,945.16	3,103.00	2,842.16	47.81
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,705.00		
Global Sum Settlement (S\$)		3,700.00		

INSPECTION

Date of Assignment: 12/10/2022
Date Inspected: 12/10/2022 Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S REAR SIDE PANEL (FRONT)	Dented	845.50 FL	*845.50 FL
2	1		*N/S REAR SIDE PANEL (REAR)	Badly Dented / Cracked	1,455.10 FL	*1,455.10 FL
3	1		*REAR BUMPER	Grazed	427.70 FL	*427.70 FL
4	1		*REAR TYRE N/S	Serviceable	300.00 FS	*- FS
5	1		*REAR TYRE RIM N/S	Repair	230.00 FS	*- FS
6	2		*TUBE N/S SIDE PANEL GLASS SEALANT	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,378.30	2,788.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	682.08	682.08
Total Parts (\$\$)	2,696.22	2,106.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	200.00	100.00
2	TO REMOVE AND REFIT N/S SIDE PANEL GLASS	New	260.00	120.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,500.00	800.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	900.00	500.00
			Gross Labour Cost (\$\$)	2,860.00
				1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >