


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: CB 7828L
 at Workshop m/s Tan Jun 9.30
 of _____
 Insured: SLL 8314L
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: CB7828L Yr Regn: 25/11/16
 Type: M.Car / M.Cycle (Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Toyota hiace commuter 2982
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 271168 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KDH 2230029602
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$54k.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 960b
 Date: _____ Person Contacted: LTAO
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA (MIC) OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 11/10/22 D.O.I. 12/10/22
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 n/s Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

19/10/22 2/s \$2900 inform sharon.
 Date / Time Action / Instruction 207 13k.

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair:

1) Date/Time, File Return to?
 2) _____

Resurvey No. of Trip:

Survey Fee: _____
 Transportation: _____
) ___ S + RS, ___ SI
) Photos
) Others
) _____
 TOTAL _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : _____
 Lump Sum / I.B.I: (\$) _____)

AIGAsia Insured's Veh No : SLL8314L
 Date of Accident : 11 October 2022

*not allowed
 due
 12/10/22
 1/5 @ 2900
 4 days.*


TAN LIM MOTOR PTE LTD
 1 Defu Lane 6 Singapore 539365
 Tel : 68585151 (24 Hours) Fax : 68580877
 GST Regn. No. : M2-8922054-2

Mr Goh Seow Nung

Date : 13 October 2022

Estimate To Repair CB7828L - Toyota Hiace Commuter GL 3.0 A
 Chassis No : KDH2230029602

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	n/s rear side panel (front) <i>DD</i>	\$ 845.50
02	1 pc	n/s rear side panel (rear) <i>Body DD/CNE</i>	\$ 1,455.10
03	1 pc	rear bumper <i>groed</i>	\$ 427.70
		Less 25 %	\$ 2,728.30
			\$ 682.08
			\$ 2,046.23
<u>SPECIAL NETT ITEMS</u>			
04	1 pc	rear bumper spare tyre <i>NIS</i>	\$ 300.00
05	1 pc	rear bumper spare tyre rim <i>AU</i>	\$ 230.00
06	2 tube	n/s side panel glass sealant @ \$60.00 <i>RM</i>	\$ 120.00
			\$ 650.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 200.00
02		To remove and refit n/s side panel glass	\$ 260.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,500.00
04		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 2,860.00
		Total	\$ 5,556.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*7- 2046.22
 60
 1520
 3826.22
 252
 2900*