

ASS. R. = UBI Typist

REF: C8/UP220/0005/Tg 33

# ASSIGNMENT

2031 Jan

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate of Cost: \_\_\_\_\_

OD / ☒ PWS / TP RES / OD RES / EVA / INV / MV

To Insp. at Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

888K

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

5

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

SKA4436P

Yr Regn: \_\_\_\_\_

2011 / Feb.

Type: ☒ Car / ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_

Peugeot 308CC

C.C. 1598

Colour \_\_\_\_\_

White

A/C: Insured / Std / NI / NA

Sp. Reading \_\_\_\_\_

143589

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

VF34B5 FVNA S209056

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ N/A / Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: 235 / 40 R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal. \_\_\_\_\_

6

mm

R/Bal. \_\_\_\_\_

- 6

mm

L/Bal. \_\_\_\_\_

6

mm

L/Bal. \_\_\_\_\_

6

mm

D.O.A. \_\_\_\_\_

D.O.I. \_\_\_\_\_

11/10/22 @ 330pm

Survey held at \_\_\_\_\_

Prompt Auto

Des. of Damages ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ WC / ☒ Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Marcus INFORMED ROY LUMPSUM \$4900.00 AND 05 DAYS. (Red \$7120.70, 59%)

Date/Time, File Pass to?



: Preli. Report

1) 30/03 Typist



: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

5

Resurvey No. of Trip: \_\_\_\_\_

1

Add Fee: \_\_\_\_\_



: Site Insp (\$ \_\_\_\_\_)



: Interview (\$ \_\_\_\_\_)



: Tech. Invs (\$ \_\_\_\_\_)



: Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL \_\_\_\_\_

Report Format: TP

Lump Sum / L.S. / L.P. 4900

# Prompt Auto Solutions Pte Ltd

8 Kaki Bukit Avenue 4 #02-37 @ Kaki Bukit (415875)

Tel: 97319322 - ROY CHAK

E-mail: promptautosolutions@gmail.com

## REPAIR ESTIMATE

TO :	DATE :
ATTENTION :	JOB TYPE : THIRD PARTY
<b>VEHICLE DETAILS</b>	
VEHICLE NO: SKA4436P	DATE :
MAKE / MODEL: Peugeot 308cc	TIME :
CHASSIS NO: VF348SFVAAS209056	
<b>ACCIDENT DETAILS</b>	

S/N	DESCRIPTIONS	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Tailgate	1	\$ 66	1,856.00
2	Tailgate "Peugeot" emblem	1	\$ 24	78.00
3	Tailgate centre emblem	1	\$ 21	93.00
4	Tailgate "308cc" emblem	1	\$ 24	48.00
5	Tailgate outer garnish	1	\$ 394	394.00
6	Tailgate outer garnish chrome moulding	1	\$ 183	183.00
7	Tailgate weatherstrip	1	\$ 196	196.00
8	Tailgate lock	1	\$ 153	153.00
9	Tailgate lock catch	1	\$ 46	46.00
10	Tailgate RH number plate lamp	1	\$ 44	44.00
11	Tailgate LH number plate lamp	1	\$ 44	44.00
12	Rear bumper	1	\$ 1,550	1,550.00
13	Rear bumper lower garnish	1	\$ 457	457.00
14	Rear bumper towing cover	1	\$ 17	17.00
15	Rear bumper RH side reverse sensor	1	\$ 191	191.00
16	Rear bumper RH centre reverse sensor	1	\$ 191	191.00
17	Rear bumper LH centre reverse sensor	1	\$ 191	191.00
18	Rear bumper LH side reverse sensor	1	\$ 191	191.00
19	Rear bumper reverse sensor holders	4	\$ 88	352.00
20	Rear bumper RH side retainer	1	\$ 63	63.00
21	Rear bumper LH side retainer	1	\$ 63	63.00
22	Rear bumper inner centre bracket	1	\$ 91	91.00
23	Rear bumper reinforcement	1	\$ 342	342.00
24	RH taillamp assy	1	\$ 463	463.00
25	LH taillamp assy	1	\$ 463	463.00
26	End panel	1	\$ 674	674.00
27	End panel inner garnish	1	\$ 178	178.00
28	Exhaust silencer	1	\$ 973	973.00
29	Exhaust silencer gasket	1	\$ 37	37.00

Rear bumper lamp LH assy

TOTAL PRICE: \$ 9,358.00  
 LIST LESS 10%: \$ 935.80  
**SUB TOTAL PRICE: \$ 8,422.20**

S/N	DESCRIPTIONS	QTY	UNIT S/N PRICE	TOTAL S/N PRICE
1	Rear number plate	1		\$ K n n 70.00
2	Rear bumper clips	1set		\$ <del>lower</del> 70.00
3	End panel joint seal	1		\$ K n n 60.00

S/N TOTAL PRICE: \$ 200.00

S/N	DESCRIPTIONS	PRICE
1	Labour charges on affected areas and replaced parts as listed	\$ <del>1600</del> 1,200.00
2	Re-spray affected areas and parts	\$ 700 1,200.00
3	Check wiring and lighting system	\$ 30 60.00
4	Apply anti rust chemical coating	\$ 40 80.00
5	Remove and replace tailgate inner mechanism to new tailgate	\$ 60 150.00
6	Remove and replace rear bumper reverse sensors and holders	\$ 40 100.00
7	Remove and replace rear inner garnish and cover	\$ 60 280.00
8	Remove and replace exhaust silencer and gasket	\$ 2 180.00

LABOUR TOTAL PRICE: \$ 3,250.00

#### ESTIMATE REPORT

TOTAL PARTS PRICE : \$ 8,622.20  
TOTAL LABOUR PRICE : \$ 3,250.00  
TOTAL AMOUNT : \$ 11,872.20

#### APPROVED DETAILS

NO. OF REPAIR DAYS :  
P & P OR LUMP SUM :  
SURVEYED BY :  
CONTACT NUMBER :

**EMAIL**  
**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfer 93495749  
WP' 11/10/2020 330pm  
c/s Resurvey after repair  
tanfer@lkkauto.com  
To check consistency of accident  
To check part prices  
5 days