



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8911B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	DENTED	2,549.70	2,549.70
1	BOOT LID RUBBER	DEFORMED	187.40	187.40
2	BOOT LID HINGE (LH/RH) @\$71.30	NOT NECESSARY	142.60	-
2	BOOT LID ABSORBER (LH/RH) @\$86.70	NOT NECESSARY	173.40	-
1	BOOT LID LOCK UPPER	DAMAGED	224.00	224.00
1	BOOT LID 'H' EMBLEM	NECESSARY	28.00	28.00
1	EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	REAR SPOILER	NOT NECESSARY	665.40	-
1	THIRD BRAKE LIGHT	NOT NECESSARY	385.60	-
1	BOOT HANDLE	NOT NECESSARY	31.80	-
2	BOOT LID LAMP (LH/RH) @\$822.00	MTG CRACKED	1,644.00	1,644.00
1	BOOT LID TRIMBOARD	MTG CRACKED	259.70	259.70
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00
1	BOOT LID TRIMBOARD, CENTRE	NOT NECESSARY	159.60	-
2	BOOT LID TRIMBOARD SIDE (LH/RH) @\$92.50	NOT NECESSARY	185.00	-
1	BOOT LID TRIMBOARD REAR	NOT NECESSARY	124.80	-
1	BOOT LID GLASS UPPER MOULDING	NOT NECESSARY	186.30	-
1	BOOT LID GLASS LOWER MOULDING	NOT NECESSARY	145.20	-
1	REAR BUMPER	DENTED / BROKEN	459.40	459.40
1	REAR BUMPER REINFORCEMENT	BROKEN	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$188.10	DENTED / BENT	376.20	376.20
1	ANTENNA ASSY-SMARTK OUTER	MTG BROKEN	689.50	689.50
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	SERVICEABLE	155.00	-
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
2	REAR BUMPER SIDE RETAINER (LH/RH) @\$85.80	SERVICEABLE	171.60	-
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE	MTG BROKEN	123.85	123.85
2	REAR BUMPER SIDE UNDER (LH/RH) @\$123.10	NOT NECESSARY	246.20	-

Report Ref No. CS/AGI22010009/Dqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER REAR HOOK	NOT NECESSARY	94.60	-
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$82.90	NOT NECESSARY	165.80	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	98.80	-
1	REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	SOCKET BROKEN	328.60	328.60
1	LICENCE LAMP	MTG BROKEN	193.53	193.53
2	TAIL LAMP (LH/RH) @\$935.40	MTG BROKEN	1,870.80	1,870.80
2	TAIL LAMP QUARTER PANEL (LH/RH) @\$208.90	NOT NECESSARY	417.80	-
1	REAR PANEL	DENTED	532.00	532.00
1	ANTENNA ASSY - TRUNK	NOT NECESSARY	689.50	-
1	REAR PANEL GARNISH	DEFORMED / BENT	346.80	346.80
1	SPARE TYRE HOLDER	NOT NECESSARY	223.10	-
1	SPARE WHEEL LOCK NUT	NOT NECESSARY	89.50	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	892.50	-
1	SPARE TYRE PANEL CUSHION	BENT	692.50	692.50
1	REAR TRAY TOOLS BOX RH	BENT	675.30	675.30
1	REAR TRAY TOOLS BOX LH	NOT NECESSARY	693.20	-
1	REAR TRAY LUGGS CENTER	NOT FITTED	354.20	-
1	LICENCE LAMP WIRE (ADDITIONAL)	SOCKET BROKEN	135.80	135.80
1	REAR FENDER INNER TRIM BOARD (RH) (ADDITIONAL)	TORN	788.75	788.75
1	ASSY BSD SPOT RADAR (RH) (ADDITIONAL)	BRACKET BENT	1,784.40	1,784.40
	LESS 20% DISCOUNT		-4,290.90	-2,964.98
			17,163.58	11,859.90
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE CAMERA ASSY (SN)	NOT NECESSARY	983.20	-
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	35.00	35.00
1	BOOT LID CAB LINK NO. STICKER (SN)	NOT NECESSARY	30.00	-
1	REAR NO. PLATE + TRIM COVER (SN)	CRACKED	45.00	45.00
2	REAR WINDSCREEN SEALANT @\$46.00 (SN)	NECESSARY	92.00	92.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	180.00	180.00

Report Ref No. CS/AGI22010009/Dqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE PANEL TOP COVER SILICON (SN)	NOT NECESSARY	250.00	-
			1,665.20	402.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL.		1,600.00	800.00
	SPRAY PAINTING CHARGE.		1,200.00	600.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.		240.00	120.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	40.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR. (ADDITIONAL)	REPEATED	550.00	-
			4,690.00	1,860.00
GRAND TOTAL			23,518.78	14,121.90

RECOMMENDED COST OF REPAIRS			14,121.90
------------------------------------	--	--	------------------

Report Ref No. CS/AGI22010009/Dqy3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.