

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010015/DNY3Q2**Date:** 13/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00012762200
Claimant Vehicle No :	SNF2647Z	Insured Vehicle No :	SNA6427S
Date of Loss:	08/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207231/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF2647Z	Engine No:	1AZE181549
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Chassis No:	MR053BK4107061654
Reg. Date:	27/01/2011 (Man. Year: 2010)	Odometer:	197945 km
Colour:	Brown		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,842.01	2,025.60	8,816.41	81.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,470.00	1,200.00	4,270.00	78.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,312.01	3,225.60	13,086.41	80.23
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	16,312.01	2,500.00	13,812.01	84.67
+ GST 7.00/7.00% (S\$)	1,141.84	175.00	966.84	84.67
Nett Amount (S\$)	17,453.85	2,675.00	14,778.85	84.67

INSPECTION

Date of Assignment:	11/10/2022	
Date Inspected:	11/10/2022 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2023)
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF2647Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,390.43 FL	*- FL
2	1		*BOOTLID DETECTOR	Not Necessary	314.59 FL	*- FL
3	2		*BOOTLID REFLECTOR L+R	Not Necessary	996.64 FL	*- FL
4	1		*BOOTLID CAMRY EMBLEM	Not fitted	95.78 FL	*- FL
5	1		*BOOTLID 2.0 EMBLEM	Not fitted	73.88 FL	*- FL
6	1		*BOOTLID LOGO	Necessary	102.30 FL	*92.50 FL
7	1		*BOOTLID LOCK	Not Necessary	486.52 FL	*- FL
8	2		*BOOTLID STOPPER	Not Necessary	58.44 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Not Necessary	489.04 FL	*- FL
10	1		*BOOTLID CENTER CHROME MOULDING	Not Necessary	317.84 FL	*- FL
11	1		*BOOTLID CENTER MOULDING	Not Necessary	416.26 FL	*- FL
12	1		*REAR BUMPER	Distorted / Cracked	884.29 FL	*681.30 FL
13	1		*REAR BUMPER REFLECTOR L/H	Not Necessary	163.49 FL	*- FL
14	1		*REAR BUMPER SIDE RETAINER L/H	Serviceable	98.25 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT BAR	Dented	792.57 FL	*420.70 FL
16	1		*TAIL LAMP L+R	O/SMtg Cracked/N/SSNotNecessary	1,678.58 FL	*546.30 FL
17	2		*TAIL LAMP PANEL L+R	Not Necessary	948.58 FL	*- FL
18	2		*TAIL LAMP LOWER GARNISH L+R	Not fitted	498.52 FL	*- FL
19	1		*REAR END PANEL	Repair	894.81 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	405.73 FL	*- FL
21	2		*REAR FENDER INNER TRIM L+R	Not Necessary	1,389.48 FL	*- FL
22	1		*REAR NUMBER PLATE	Not Necessary	90.00 FS	*- FS
23	1		*SET REAR REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
24	1		*WRAP STICKERS BOOT LIP+ BUMPER	Necessary	800.00 FS	*500.00 FS
25	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*FENDER SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*TAIL PANEL SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,966.02	2,460.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,124.01	435.20
Total Parts (\$\$)	10,842.01	2,025.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,600.00	500.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	30.00
5	TO CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
6	TO RNR REVERSE CAMERA	New	100.00	-
7	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	0.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
9	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
11	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
Gross Labour Cost (S\$)			5,470.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >