

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22010020/RWY3Q2**Date:** 01/02/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** XE3753E **Insured Vehicle No :** SKT960T

Date of Loss: 07/10/2022 Nature of Claim: TP Claim No: DMPC2200461H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE3753E**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: GH11746590

Reg. Date: 11/12/2017 (Man. Year: 2017) Chassis No: JNCM1F1AXHU026614

Colour: White Odometer: 147205 km

Engine Capacity: 10837 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5 (D)

Front Left Side: Fenix Way 8 mm Rear Left Side: Fenix Way 8/8 mm

Front Right Side: Fenix Way 8 mm Rear Right Side: Fenix Way 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,051.70	2,805.57	2,246.13	44.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	730.00	900.00	55.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,681.70</b>	<b>3,535.57</b>	<b>3,146.13</b>	<b>47.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>(S\$)</b>	6,681.70	2,800.00	3,881.70	58.09
<b>+ GST 8.00/8.00% (S\$)</b>	534.54	224.00	310.54	58.09
<b>Nett Amount (S\$)</b>	<b>7,216.24</b>	<b>3,024.00</b>	<b>4,192.24</b>	<b>58.09</b>

INSPECTION

Date of Assignment: 10/10/2022

Date Inspected: 12/10/2022 Inspected At: Think One Autocare Pte Ltd (HQ)  
No. 60 Jalan Lam Huat #02-32, Carros Centre  
Singapore 737869

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Jan 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE3753E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CORNER BUMPER RH	Bent	1,478.00 FL	*1,300.00 FL
2	1		*FRONT HEADLAMP RH	Scratched	2,218.40 FL	*1,280.00 FL
3	1		*FRONT HEADLAMP BRACKET RH	Not Necessary	542.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	652.30 FL	*- FL
5	1		*FRONT BUMPER SIGNAL LAMP RH	Scratched	332.30 FL	*332.30 FL
6	1		*CORNER BUMPER END GARNISH RH	Scratched	205.00 FL	*205.00 FL
7	1		*CORNER BUMPER END BRACKET RH	Not Necessary	185.00 FL	*- FL
					<b>Sub Total (\$\$)</b>	<b>5,613.00      3,117.30</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>561.30      311.73</b>
					<b>Total Parts (\$\$)</b>	<b>5,051.70      2,805.57</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR ,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS /ATTACHMENTS	New	800.00	300.00
2	TO SPRAY PAINT REPLACED /REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	800.00	400.00
3	TO CONDUCT HEADLAMP ALIGNMENT	New	30.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,630.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >