

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22010025/APA3Q2**Date:** 14/06/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SLE6164C **Insured Vehicle No :** SLW5324U

Date of Loss: 06/10/2022 Nature of Claim: TP Claim No: MFL2022D0005632

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE6164C**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRY325207

Reg. Date: 27/07/2016 (Man. Year: 2016) Chassis No: MR053REH104556124

Colour: Silver Odometer: 140761 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,744.82	5,719.50	2,025.32	26.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	2,410.00	1,290.00	34.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,444.82	8,129.50	3,315.32	28.97
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	11,444.82	6,500.00	4,944.82	43.21
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		7,538.45		
Global Sum Settlement (S\$)		7,500.00		

INSPECTION

Date of Assignment: 10/10/2022

Date Inspected: 10/10/2022 Inspected At:

AUTO UNITED SG PTE LTD (HQ)
13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ
CENTRE
Singapore 417807

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE6164C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Distorted	1,270.80 FL	*1,270.80 FL
2	1		*FRONT LH DOOR LOCK	Jammed	374.50 FL	*374.50 FL
3	1		*FRONT LH DOOR WEATHERSTRIPE	Cut	230.10 FL	*230.10 FL
4	1		*FRONT LH DOOR HANDLE	Damaged	189.40 FL	*189.40 FL
5	1		*FRONT LH DOOR HANDLE END PIECE	Damaged	38.50 FL	*38.50 FL
6	1		*FRONT LH DOOR INNER TRIM BOARD	Cracked	681.40 FL	*681.40 FL
7	1		*FRONT LH DOOR GLASS OUTER CHROME MOULDING	Bent	168.10 FL	*168.10 FL
8	1		*FRONT LH DOOR GLASS REGULATOR GEAR	Damaged	291.70 FL	*291.70 FL
9	1		*FRONT LH DOOR GLASS REGULATOR MOTOR	Damaged	545.10 FL	*545.10 FL
10	1		*FRONT LH DOOR WING MIRROR	Not Necessary	1,168.20 FL	*- FL
11	1		*FRONT LH DOOR WING MIRROR COVER	Repair	118.50 FL	*- FL
12	1		*ROCKER PANEL LH	Dented	856.90 FL	*856.90 FL
13	1		*CENTRE PILLAR	Dented	699.10 FL	*699.10 FL
14	1		*CENTRE PILLAR INNER TRIM COVER (LOWER)	Not Necessary	345.20 FL	*- FL
15	1		*REAR LH DOOR	Dented	1,255.90 FL	*1,255.90 FL
16	1		*REAR LH DOOR LOCK	Not Necessary	361.70 FL	*- FL
17	1		*REAR LH DOOR WEATHERSTRIPE	Not Necessary	224.60 FL	*- FL
18	1		*REAR LH DOOR INNER TRIM DOOR BOARD	Cracked	634.10 FL	*634.10 FL
19	2		*REAR LH DOOR HINGE	Bent	150.40 FL	*150.40 FL
20	1		*REAR LH DOOR CHECK	Not Necessary	68.90 FL	*- FL
21	1		*FRONT LH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
22	1		*FRONT LH DOOR BLACK TRIM	Necessary	100.00 FS	*60.00 FS
23	1		*CENTRE PILLAR INNER TRIM COVER (LOWER) CLIPS	Not Necessary	30.00 FS	*- FS
24	1		*REAR LH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
25	1		*REAR LH DOOR BLACK TRIM	Necessary	100.00 FS	*60.00 FS
26	1		*ROCKER PANEL SEALANT	Not Necessary	100.00 FS	*- FS
27	1		*CENTRE PILLAR SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,163.10	7,566.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,418.28	1,846.50
Total Parts (\$\$)	7,744.82	5,719.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	1,200.00
2	SPRAY PAINTING	New	1,400.00	900.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	80.00
5	TO REMOVE UPHOLSTERY	New	150.00	40.00
6	TO TRANSFER FRONT & REAR DOOR FITTINGS	New	300.00	160.00
Gross Labour Cost (S\$)			3,700.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >