

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010026/KVY3Q2**Date:** 27/10/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00030442200

**Claimant Vehicle
No :** SBL6968G**Insured Vehicle
No :** SNC8287E

Date of Loss: 03/10/2022

Nature of Claim: TP

Claim
No: SNM22D207117/C02/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SBL6968G**Make & Model: MERCEDES-BENZ E200, 2.0 SEDAN AVG (R18 LED
SR) (A)

Engine No: 26492080025373

Reg. Date: 19/02/2020 (Man. Year: 2019)

Chassis No: WDD2130802A751689

Colour: Metallic Black

Odometer: 37282 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 245/45 R18

Front Left Side: Goodyear 7 mm

Rear Left Side: Goodyear 7 mm

Front Right Side: Goodyear 7 mm

Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,259.40	1,905.30	5,354.10	73.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	950.00	1,640.00	63.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,849.40	2,855.30	6,994.10	71.01
+ GST 7.00/7.00% (S\$)	689.46	199.87	489.59	71.01
Nett Amount (S\$)	10,538.86	3,055.17	7,483.69	71.01

INSPECTION

Date of Assignment: 11/10/2022

Date Inspected: 12/10/2022 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Oct 2022)

Parts: 143 MERCEDES-BENZ E200 2.0 SEDAN AVG (R18 LED SR) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBL6968G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -RH	Bent	1,150.00 FN	*1,150.00 FN
2	1		*FRONT BUMPER	Serviceable	1,975.00 FN	*- FN
3	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	24.00 FN	*- FN
4	1		*FRONT BUMPER SENSOR	Scratched	215.00 FN	*215.00 FN
5	6		*FRONT BUMPER SENSOR SEAL	Necessary (1 PCS ONLY)	72.00 FN	*12.00 FN
6	1		*HEADLAMP RH	Serviceable	3,890.00 FN	*- FN
7	1		*SPORT RIM RH	Dented	740.00 FN	*740.00 FN
					Sub Total (\$\$)	8,066.00 2,117.00
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	806.60 211.70
					Total Parts (\$\$)	7,259.40 1,905.30

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	80.00	30.00
2	TO PANEL BEAT AND STRAIGHTEN FRONT CHASSIS FRAME ,TO CUT AND WELD FRONT RH FENDER ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME	New	900.00	400.00
3	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	440.00
4	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
5	TO CHECK WHEEL ALIGNMENT BY COMPUTERISED	New	180.00	60.00
6	TO RE-PROGRAM FRONT HEADLAMP	New	350.00	0.00
Gross Labour Cost (\$\$)			2,590.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >