



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5094T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	COVER, FR BUMPER (SN)	BROKEN	560.30	560.30
1	BRACKET, FR BUMPER (SN)	BROKEN	111.80	111.80
1	GRILLE, RADIATOR (SN)	BROKEN	183.90	183.90
1	SUPPORT, FR BUMPER (O/S) (SN)	DENTED	86.20	86.20
1	SUPPORT, FR BUMPER (N/S) (SN)	NOT NECESSARY	86.20	-
10	PIECE, RR BUMPER @\$4.80 (SN)	NECESSARY	48.00	45.00
2	RETAINER, FR BUMPER @\$9.50 (SN)	BROKEN	19.00	19.00
1	COVER, FR BUMPER (SN)	MISSING	31.80	31.80
1	COVER, FR BUMPER (SN)	MISSING	31.80	31.80
1	ABSORBER, FR BUMPER (SN)	BROKEN	143.60	143.60
1	ABSORBER, FR BUMPER (SN)	BROKEN	85.90	85.90
1	REINFORCMENT, FR (SN)	NOT NECESSARY	265.90	-
1	EXTENSION SUB-ASSY (SN)	NOT NECESSARY	129.90	-
1	EXTENSION SUB-ASSY (SN)	NOT NECESSARY	129.90	-
1	GRILLE SUB-ASSY (SN)	BROKEN	374.40	374.40
1	FENDER SUB-ASSY, FR (SN)	TO REPAIR SEE LABOUR	1,060.70	-
1	FENDER SUB-ASSY, FR (SN)	TO REPAIR SEE LABOUR	1,005.20	-
1	LINER, FR FENDER, RH (SN)	TORN	223.50	223.50
1	LINER, FR FENDER, LH (SN)	TORN	219.10	219.10
1	UNIT, HEADLAMP (SN)	BROKEN	2,852.40	2,852.40
1	UNIT, HEADLAMP (SN)	BROKEN	2,852.40	2,852.40
1	LAMP ASSY, FOG, RH (SN)	BROKEN	1,029.90	1,029.90
1	LAMP ASSY, FOG, LH (SN)	NOT NECESSARY	1,029.90	-
1	EMBLEM ASSY (SN)	NECESSARY	98.70	98.70
1	FRONT REGN PLATE (PO# ) (SN) (ADDITIONAL)	DENTED	80.00	80.00
1	SUPPORT S/A (SN) (ADDITIONAL)	CRACKED	265.10	265.10
1	SUPPORT S/A (SN) (ADDITIONAL)	CRACKED	265.10	265.10
1	SUPPORT S/A (SN) (ADDITIONAL)	CRACKED	408.50	408.50

Report Ref No. CS/SMR22010027/Ecy3m4



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUPPORT, RADIATOR (SN) (ADDITIONAL)	CRACKED	85.20	85.20
1	SUPPORT, RADIATOR (SN) (ADDITIONAL)	CRACKED	85.20	85.20
1	INLET, AIR CLEANER (SN) (ADDITIONAL)	CUT	45.60	45.60
1	INLET, AIR CLEANER (SN) (ADDITIONAL)	CUT	122.10	122.10
1	SEAL, HOOD TO FR END (SN) (ADDITIONAL)	NECESSARY	55.80	55.80
1	HOUSING, CONNECTOR (SN) (ADDITIONAL)	CUT	32.70	32.70
1	GUIDE, RADIATOR AIR (SN) (ADDITIONAL)	CRACKED	75.90	75.90
1	GUIDE, RADIATOR AIR (SN) (ADDITIONAL)	CRACKED	70.70	70.70
1	SEAL, RADIATOR TO (SN) (ADDITIONAL)	NECESSARY	32.10	32.10
1	SEAL, RADIATOR TO (SN) (ADDITIONAL)	NECESSARY	32.10	32.10
			14,416.50	10,655.80
	<b>LABOUR</b>			
	CHECK WIRING & CONDUCT LEAK TEST.		180.00	180.00
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA. INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY, FR.		2,880.00	1,800.00
	RESPRAY ACC AFF AREA.		2,950.00	2,360.00
			6,190.00	4,520.00
	<b>GRAND TOTAL</b>		<b>20,606.50</b>	<b>15,175.80</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>15,175.80</b>

Report Ref No. CS/SMR22010027/Ecy3m4

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.