

ASS. REC. BY:

REF:

LPC / 22010030/Kgys

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11-11-30cm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKA 6996B

Yr Regn:

06/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Estima

c.c.

2362

Colour

m. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

52796

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ACR50

0190232

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Falken

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

29/9/22

D.O.I.

17/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Tailgate jammed.

23/12 11:30 84400 Carport (Red, \$2388.50, 35%)

Date/Time, File Pass to?

1) 5/1/23 ☐ : Prell. ReportDate/Time, File Return to? ☐ : Final Report

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

OD

Lump Sum / I.B.I. (\$

4400

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	205F
Vehicle Details	
Vehicle No.:	SKA6996B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2AZJ147595
Chassis No.:	ACR500190232
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$29,018.00
Original Registration Date:	19 Jun 2015
First Registration Date:	19 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$32,626.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2025
PARF Rebate Amount:	\$19,575.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$78,001.00
COE Rebate Amount:	\$21,232.00
Total Rebate Amount:	\$40,807.00

The information contained herein is correct as at 29 Sep 2022

OK

Not Authorized
 61 hrs @ 4000
 Pending After Repair
 Ex @ 6000
 6 days



The Motor Claims Department
 M/s Lonpac Insurance Bhd
 300 Beach Road, #17-04/07
 The Concourse
 Singapore 199555

File No :

Date : 07-October-2022

Estimated cost of repair for vehicle no : SKA6996B Toyota Estima

Policy no: Z22VP05031418

Accident Date: 29.09.2022

Description	Quantity	Cost Price
Tailgate	1	\$ R 680.00 ✓
Tailgate emblem	1	\$ R 40.00 ✓
Tailgate badge "estima"	1	\$ R 40.00 ✓
Tailgate badge "aeras"	1	\$ R 40.00 ✓
Tailgate inner lock	1	\$ R 190.00 ✓
Tailgate weatherstrip	1	\$ DSI/WT 150.00 ✓
Tailgate inner trim board	1	\$ M/CMT 350.00 ✓
Rear windscreen moulding	1	\$ R 75.00 ✓
Rear bumper	1	\$ R 280.00 ✓
Rear bumper clips (1 set)	1	\$ R 15.00 ✓
Rear bumper tow cover	1	\$ R 20.00 ✓
RH Rear bumper reflector	1	\$ R 40.00 X
LH Rear bumper reflector	1	\$ CM 40.00 ✓
RH Rear bumper sponge	1	\$ CM 55.00 ✓
LH Rear bumper sponge	1	\$ CM 55.00 ✓
RH Rear bumper retainer	1	\$ DIT 45.00 ✓
LH Rear bumper retainer	1	\$ DIT 45.00 ✓
RH Rear bumper bracket	1	\$ R 40.00 X
LH Rear bumper bracket	1	\$ R 40.00 X
Rear end panel	1	\$ R 280.00 ✓
Rear end panel top trim	1	\$ R 180.00 ✓
Rear floor panel	1	\$ R 450.00 X
Rear floor panel top trim board	1	\$ R 250.00 ✓
		\$ 3,400.00
	Add 15%	\$ 510.00
		\$ 3,910.00
Rear bumper parking sensors (1 set)	1	S. nett \$ CM 280.00 2000
Rear windscreen sealant	1	S. nett \$ R 60.00 8000
Rear windscreen inner seal	1	S. nett \$ R 28.00 ✓

To remove and reinstall rear windscreen and conduct water leak test	\$	120.00	✓
To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member, to replace damaged parts and adjust rear body and tailgate alignment	\$	650.00	600
To spray paint affected rear and inner damaged portion inclusive of preparatory works and material	\$	800.00	750
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality	\$	50.00	20
To perform computer diagnostic on parking system, ABS systems, and clear fault codes	\$	150.00	~ X
To apply anti-corrosion Tuff-Kote	\$	80.00	~ X
	\$	6,128.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6788.50