

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 8421H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,050.00	-
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	40.00	-
1	FOG LAMP COVER RH	CRACKED	155.00	155.00
1	FRONT FOG LAMP RH	NOT NECESSARY	295.00	-
1	FRONT BUMPER LAMP RH	NOT NECESSARY	225.00	-
1	FRONT TOWING COVER	NOT NECESSARY	25.00	-
	LESS 20% DISCOUNT		-358.00	-31.00
			1,432.00	124.00
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
1	SUNDRIES (SAND PAPER, WELDING WIRE ETC.) (SN)	NOT NECESSARY	50.00	-
			100.00	-
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		600.00	200.00
	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIT FRONT BUMPER PARKING SENSORS.	NOT NECESSARY	80.00	-
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		400.00	200.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	40.00	-
	TO VACUUM, WAXING & CLEAN.	NOT NECESSARY	60.00	-
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS.	NOT NECESSARY	50.00	-
			1,330.00	400.00
	GRAND TOTAL		2,862.00	524.00

Report Ref No. CS/SMR22010032/Rny3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 524.00

Report Ref No. CS/SMR22010032/Rny3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator