

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 576L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER - LH	BADLY DENTED	651.20	651.20
1	FRONT FENDER DUST COVER - LH	TORN	126.40	126.40
1	SET FRONT FENDER DUST COVER CLIP - LH	NECESSARY	77.40	40.00
1	FRONT HEADLAMP - LH	CRACKED	543.90	543.90
1	FRONT GRILLE	NOT NECESSARY	313.90	-
1	FRONT BUMPER	DISTORTED	481.60	481.60
1	FRONT BUMPER TOP RUBBER SEAL	TORN	56.60	56.60
2	FRONT BUMPER SIDE RETAINER @\$51.60	CRACKED	103.20	103.20
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	342.70	-
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	206.20	-
1	SET FRONT BUMPER CLIP	NECESSARY	51.60	40.00
1	FRONT BUMPER LOWER CENTRE GRILLE	TWISTED	102.90	102.90
1	FRONT BUMPER UNDER DUST COVER	TORN	246.60	246.60
1	SET FRONT BUMPER UNDER DUST COVER CLIP	NECESSARY	77.40	40.00
1	FRONT FENDER EMBLEM - LH	NECESSARY	229.60	68.00
	LESS 25% DISCOUNT		-902.80	-625.10
			2,708.40	1,875.30
	<u>LABOUR</u>			
	TOWING.	NOT NECESSARY	50.00	-
	PANEL BEATING.		850.00	380.00
	RUST PROOFING.		60.00	30.00
	CHECK WIRING.		60.00	20.00
	TO SPRAY PAINTING.		750.00	450.00
			1,770.00	880.00
	GRAND TOTAL		4,478.40	2,755.30

Report Ref No. CS/FCI22010036/Uqy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI22010036/Uqy3m4

MARKET VALUE: \$15,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$5,163.00=NETT VALUE: \$9,837.00

CHUA KANG SENG

**Licensed Appraiser**