

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010038/APA3Q2**Date:** 20/12/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070126346
Claimant Vehicle No :	SLS6438P	Insured Vehicle No :	GBK5242D
Date of Loss:	03/10/2022	Nature of Claim:	TP
		Claim No:	5134344774SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6438P		
Make & Model:	VOLKSWAGEN PASSAT, 1.8 B8 TFSI AT SR 17W 3G24JZ HUD (A)	Engine No:	CJS192019
Reg. Date:	29/09/2017 (Man. Year: 2016)	Chassis No:	WVWZZZ3CZHE117481
Colour:	White	Odometer:	54521 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,404.74	14,058.86	12,345.88	46.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,380.00	3,140.00	3,240.00	50.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,784.74	17,198.86	15,585.88	47.54
Approved Total (Overridden) (\$\$)		13,700.00		
Nett Amount (\$\$)	32,784.74	13,700.00	19,084.74	58.21
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	04/10/2022	
Date Inspected:	04/10/2022 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	11.0 days	

Adjuster: ADRIAN LING**Manager:** CHEN TSUE YEE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR CHECKER LH	Not Necessary	190.63 FL	*- FL
2	1		*FRONT DOOR PROTECTOR CHROME LH	Not Necessary	228.00 FL	*- FL
3	1		*SIDE SKIRT LH	Deformed	1,062.35 FL	*755.00 FL
4	1		*SIDE SKIRT MOULDING LH	Deformed	352.00 FL	*352.00 FL
5	1		*REAR DOOR LH	Distorted	1,880.00 FL	*1,880.00 FL
6	2		*REAR DOOR HINGE LH	Not Necessary	253.50 FL	*- FL
7	1		*REAR DOOR WEATHER STRIP LH	Necessary	308.53 FL	*308.53 FL
8	1		*REAR DOOR LOCK CATCHER LH	Not Necessary	63.68 FL	*- FL
9	1		*REAR DOOR SPEAKER LH	Not Necessary	142.53 FL	*- FL
10	1		*REAR DOOR INNER LOCK LH	Damaged	476.68 FL	*476.68 FL
11	1		*REAR DOOR GLASS REGULATOR GEAR MOTO LH	Damaged	732.38 FL	*732.38 FL
12	1		*REAR DOOR OUTER HANDLE LH	Damaged	387.55 FL	*387.55 FL
13	1		*REAR DOOR OUTER MOULDING LH	Not Necessary	167.28 FL	*- FL
14	1		*REAR DOOR LOWER PROTECTOR LH	Deformed	208.00 FL	*208.00 FL
15	1		*REAR DOOR LOWER CHROME LH	Cut	388.00 FL	*388.00 FL
16	1		*REAR DOOR BOTTOM STRIP LH	Cut	189.73 FL	*189.73 FL
17	1		*REAR DOOR GLASS CHANNEL LH	Not Necessary	426.43 FL	*- FL
18	1		*REAR DOOR INNER TRIM BOARD LH	Cracked	1,397.62 FL	*780.00 FL
19	1		*REAR WINDSCREEN C/W MOULDING	Necessary	1,896.30 FL	*245.00 FL
20	1		*REAR FENDER LH	Distorted	1,819.58 FL	*1,819.58 FL
21	1		*REAR FENDER INNER PANEL LH	Dented	685.30 FL	*685.30 FL
22	1		*REAR FENDER COWLING	N/S Deformed	539.58 FL	*269.79 FL
23	1		*REAR FENDER INNER TRIM LH	Not Necessary	476.50 FL	*- FL
24	1		*REAR FENDER AIR VENT LH	Not Necessary	97.35 FL	*- FL
25	1		*REAR BUMPER	Deformed	1,400.77 FL	*1,400.77 FL
26	1		*REAR BUMPER REFLECTOR LH	Not Necessary	114.30 FL	*- FL
27	1		*REAR BUMPER DIFFUSER	Not Necessary	225.00 FL	*- FL
28	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	197.50 FL	*98.75 FL
29	1		*REAR BUMPER SIDE CHROME LH	Not Necessary	260.00 FL	*- FL
30	1		*REAR WHEEL RIM LH	Cut	1,520.55 FS	*700.00 FS
31	1		*REAR ABS SENSOR LH	Not Necessary	380.90 FL	*- FL
32	1		*REAR CROSSMEMBER	Not Necessary	2,596.71 FL	*- FL
33	1		*REAR LOWER ARM LH	Bent	697.43 FL	*697.43 FL
34	1		*REAR SWING ARM LH	Bent	658.30 FL	*658.30 FL
35	1		*REAR SHOCK ABSORBER LH	Not Necessary	696.31 FL	*- FL
36	1		*REAR WHEEL HUP	Damaged	674.63 FL	*674.63 FL
37	1		*REAR WHEEL HUP BEARING LH	Damaged	494.51 FL	*494.51 FL
38	1		*REAR UPPER ARM LH	Not Necessary	659.21 FL	*- FL
39	1		*REAR CONTROL ARM LH	Bent	745.33 FL	*245.00 FL
40	1		*REAR KNUCKLE ARM LH	Damaged	796.25 FL	*796.25 FL
41	1		*REAR LINKAGE LH	Not Necessary	214.31 FL	*- FL
42	1		*TAIL LAMP LH	Not Necessary	479.25 FL	*- FL
43	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
44	1		*REAR DOOR SEALANT RH	Necessary	80.00 FS	*30.00 FS
45	1		*SET REAR DOOR TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
46	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
47	1		*REAR WINDSCREEN INNER SHIELD	Not Necessary	80.00 FS	*- FS
48	1		*REAR FENDER SEALANT LH	Necessary	150.00 FS	*40.00 FS
49	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
50	1		*REAR FENDER INNER PANEL SEALANT LH	Not Necessary	120.00 FS	*- FS
51	1		*SET REAR FENDER COWLING CLIP	Necessary	80.00 FS	*30.00 FS
52	1		*REAR DOOR PROTECTOR CLIP	Necessary	50.00 FS	*20.00 FS
53	1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
54	1		*FRONT DOOR PROTECTOR CLIP	Not Necessary	60.00 FS	*- FS
55	1		*SET SIDE SKIRT CLIPS	Necessary	80.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

12/20/22, 11:09 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR WHEEL TYRE LH	Not Necessary	680.00 FS	*- FS
57	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					28,970.76	15,513.18
- List Item Discount on L Items 10.00/10.00% (\$)					2,566.02	1,454.32
Total Parts (\$)					26,404.74	14,058.86
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ADJUST KNOCK	New	1,800.00	1,200.00
2	TO SPRAY PAINT	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	80.00
4	WIRING BULB CHECKING	New	180.00	30.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	100.00
6	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
7	REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
8	TRANFER REAR DOOR MECHANISM RH	New	80.00	40.00
9	REMOVE & REINSTALL REAR DOOR WINDOW GLASS RH	New	60.00	40.00
10	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	220.00
11	FOUR WHEEL ALIGNMENT	New	120.00	80.00
12	REMOVE AND REFIX REVERSE SENSOR	New	80.00	50.00
13	RESET ABS LIGHT	New	350.00	0.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	400.00	180.00
Gross Labour Cost (\$\$)			6,380.00	3,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >