

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010040/APA3Q2**Date:** 11/05/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070092462
Claimant Vehicle No : GBJ1077X **Insured Vehicle No :** GBJ6029C
 Date of Loss: 05/10/2022 Nature of Claim: TP Claim No: 2956022395SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ1077X**
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2838421
 Reg. Date: 03/01/2019 (Man. Year: 2018) Chassis No: JTFAT35Y00K212372
 Colour: Silver Odometer: 78212 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C
 Front Left Side: Bridgestone 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,808.95	12,111.35	14,697.60	54.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,000.00	2,630.00	4,370.00	62.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,808.95	14,741.35	19,067.60	56.40
Approved Total (Overridden) (S\$)		11,800.00		
Nett Amount (S\$)	33,808.95	11,800.00	22,008.95	65.10
+ Car Rental (10.0 x S\$90.00/day + 7.00% GST) (S\$)		963.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,770.45		
Global Sum Settlement (S\$)		12,700.00		

INSPECTION

Date of Assignment: 06/10/2022
 Date Inspected: 06/10/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Shattered	1,495.00 FL	*1,322.00 FL
2	1		*FRONT WINDSCREEN RUBBER	Necessary	365.00 FL	*365.00 FL
3	1		*FRONT WIPER PANEL	Distorted	594.60 FL	*594.60 FL
4	1		*FRONT WIPER HEAD C/W LINKAGE	Bent	364.20 FL	*364.20 FL
5	2		*FRONT WIPER ARM	Not Necessary	359.60 FL	*- FL
6	2		*FRONT WIPER BOLT COVER	Not Necessary	48.20 FL	*- FL
7	1		*FRONT WIPER NOZZLE	N/S Cracked	139.40 FL	*69.70 FL
8	2		*FRONT WIPER BLADE	Cut	149.00 FL	*149.00 FL
9	1		*FRONT PANEL	Distorted	1,010.40 FL	*1,010.40 FL
10	1		*FRONT PANEL EMBLEM DYNA	Necessary	75.80 FL	*75.80 FL
11	2		*FRONT CORNER GARNISH	Not Necessary	659.60 FL	*- FL
12	1		*FRONT GRILLE	Cracked	795.20 FL	*795.20 FL
13	1		*FRONT GRILLE LOGO	Necessary	96.20 FL	*96.20 FL
14	1		*FRONT WIRE HARNESS	Not Necessary	1,965.30 FL	*- FL
15	1		*FRONT CABIN HINGE	Not Necessary	2,640.10 FL	*- FL
16	1		*SET FRONT CABIN LOCK	Not Necessary	1,217.60 FL	*- FL
17	1		*FRONT FLOOR PANEL	Repair	2,414.40 FL	*- FL
18	1		*FRONT CHASSIS CROSS MEMBER	Not Necessary	1,360.00 FL	*- FL
19	2		*HEAD LAMP	Cracked	1,938.40 FL	*1,938.40 FL
20	2		*HEAD LAMP LOWER RUBBER	Not Necessary	94.40 FL	*- FL
21	1		*FRONT BUMPER	Deformed	727.10 FL	*727.10 FL
22	2		*FRONT BUMPER BRACKET	N/S Bent	506.60 FL	*253.30 FL
23	1		*FRONT BUMPER FOGLAMP COVER	N/S Missing	190.60 FL	*95.30 FL
24	1		*FRONT DOOR PILLAR LH	Repair	894.50 FL	*- FL
25	1		*FRONT DOOR LH	Not Necessary	1,796.70 FL	*- FL
26	1		*FRONT DOOR INNER LOCK LH	Not Necessary	306.40 FL	*- FL
27	1		*FRONT DOOR WINDOW GLASS LH	Not Necessary	725.90 FL	*- FL
28	1		*FRONT DOOR INNER TRIM LH	Not Necessary	942.80 FL	*- FL
29	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	195.60 FL	*- FL
30	1		*SIDE MIRROR (SQUARE) LH	Not Necessary	398.50 FL	*- FL
31	1		*SIDE MIRROR (ROUND) LH	Cracked	243.50 FL	*243.50 FL
32	1		*SIDE MIRROR STAND LH	Bent	268.20 FL	*268.20 FL
33	1		*SIDE MIRROR AUTO MOTOR LH	Damaged	678.90 FL	*678.90 FL
34	1		*DASHBOARD	Cracked	1,250.40 FL	*1,250.40 FL
35	1		*DASHBOARD SIDE LOWER GARNISH LH	Not Necessary	396.40 FL	*- FL
36	1		*DASHBOARD CENTER GARNISH	Not Necessary	453.00 FL	*- FL
37	1		*AIR CON HOSE (2PCS)	Bent (1Pc Only)	793.00 FL	*396.50 FL
38	1		*AIR CON CONDENSER	Dented	864.00 FL	*864.00 FL
39	1		*AIR CON CONDENSER BRACKET	Bent	276.30 FL	*276.30 FL
40	1		*AIR CON CONDENSER FAN WITH COWLING	Cracked	489.20 FL	*489.20 FL
41	1		*AIR CON COOLING COIL	Cracked	1,782.20 FL	*1,782.20 FL
42	1		*AIR CON BLOWER	Cracked	1,356.40 FL	*1,356.40 FL
43	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*30.00 FS
44	1		*SET FRONT GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
45	1		*SET FRONT CORNER GARNISH	Not Necessary	40.00 FS	*- FS
46	1		*FRONT PANEL SEALANT	Necessary	150.00 FS	*60.00 FS
47	1		*FRONT WINDSCREEN SOLAR FILM	Necessary	550.00 FS	*200.00 FS
48	1		*FRONT ERP BRACKET	Necessary	40.00 FS	*25.00 FS
49	1		*FRONT WIPER PANEL COMPANY STICKER	Necessary	180.00 FS	*100.00 FS
50	1		*FRONT DOOR LTA STICKER LH	Necessary	40.00 FS	*30.00 FS
51	1		*SET DASHBOARD CLIP	Necessary	150.00 FS	*50.00 FS
52	1		*FRONT VIDEO CAMERA	Not Necessary	580.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **35,138.60** **15,976.80**

- List Item Discount on L Items 25.00/25.00% (\$\$) 8,329.65 3,865.45

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (\$)	26,808.95	12,111.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	New	1,800.00	800.00
2	TO PUTTY, SPRAY PAINT, POLISH WAX	New	1,400.00	1,000.00
3	TO SPRAY TUFF COAT	New	250.00	80.00
4	WIRING, BULB CHECKING	New	80.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
6	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	80.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	REMOVE AND REFIX AIRCON BLOWER, COOLING COIL AND REFILL AIRCON GAS	New	150.00	150.00
9	REMOVE AND REINSTALL DASHBOARD	New	650.00	220.00
10	TRANSFER FRONT DOOR MECHANISM	New	80.00	0.00
11	REMOVE AND REFIX DOOR WINDOW GLASS	New	80.00	0.00
12	REMOVE AND REFIX CABIN	New	1,200.00	0.00
13	REMOVE AND REFIX VIDEO SYSTEM	New	500.00	150.00
14	REMOVE AND REFIX AND RESET AUDIO SYSTEM	New	120.00	0.00
15	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	120.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			7,000.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >