

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBJ1077X**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 05.10.2022
 TIME OF ACCIDENT : 09:20 HRS

23	FRONT BUMPER FOGLAMP COVER	LH Missing	2	\$ 95.30	\$ 190.60	85.30
24	FRONT DOOR PILLAR LH	Regr	1	\$ 894.50	\$ 894.50	+
25	FRONT DOOR LH	Neu	1	\$ 1,796.70	\$ 1,796.70	+
26	FRONT DOOR INNER LOCK LH	?	1	\$ 306.40	\$ 306.40	+
27	FRONT DOOR WINDOW GLASS LH	LH	1	\$ 725.90	\$ 725.90	+
28	FRONT DOOR INNER TRIM LH	Neu	1	\$ 942.80	\$ 942.80	+
29	FRONT DOOR WEATHERSTRIP LH	Neu	1	\$ 195.60	\$ 195.60	+
30	SIDE MIRROR (SQUARE) LH	Neu	1	\$ 398.50	\$ 398.50	+
31	SIDE MIRROR (ROUND) LH	culd	1	\$ 243.50	\$ 243.50	✓
32	SIDE MIRROR STAND LH	Best	1	\$ 268.20	\$ 268.20	✓
33	SIDE MIRROR AUTO MOTOR LH	Regr	1	\$ 678.90	\$ 678.90	✓
34	DASHBOARD	culd	1	\$ 1,250.40	\$ 1,250.40	✓
35	DASHBOARD SIDE LOWER GARNISH LH	Neu	1	\$ 396.40	\$ 396.40	+
36	DASHBOARD CENTER GARNISH	Neu	1	\$ 453.00	\$ 453.00	+
37	AIR CON HOSE	Best 1 piece	2	\$ 396.50	\$ 793.00	738.5
38	AIR CON CONDENSER	Dented	1	\$ 864.00	\$ 864.00	✓
39	AIR CON CONDENSER BRACKET	Best	1	\$ 276.30	\$ 276.30	✓
40	AIR CON CONDENSER FAN WITH COWLING	culd	1	\$ 489.20	\$ 489.20	✓
41	AIR CON COOLING COIL	culd	1	\$ 1,782.20	\$ 1,782.20	✓
42	AIR CON BLOWER	culd	1	\$ 1,356.40	\$ 1,356.40	✓

15461.80
11556.35

TOTAL PRICE \$ 33,318.60
 LESS 25% \$ 8,329.65
SUB TOTAL PRICE \$ 24,988.95

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT		
1	FRONT NUMBER PLATE	Dented	1	\$ 50.00	\$ 50.00	30
2	FRONT GRILLE CLIP (SET)	Neu	1	\$ 40.00	\$ 40.00	20
3	FRONT CORNER GARNISH (SET)	Neu	1	\$ 40.00	\$ 40.00	+
4	FRONT PANEL SEALANT	Neu	1	\$ 150.00	\$ 150.00	60
5	FRONT WINDSCREEN SOLAR FILM	Neu	1	\$ 550.00	\$ 550.00	200
6	FRONT ERP BRACKET	Neu	1	\$ 40.00	\$ 40.00	25
7	FRONT WIPER PANEL COMPANY STICKER	Neu	1	\$ 180.00	\$ 180.00	100
8	FRONT DOOR LTA STICKER LH	Neu	1	\$ 40.00	\$ 40.00	30
9	DASHBOARD CLIP (SET)	Neu	1	\$ 150.00	\$ 150.00	50

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBJ1077X**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 05.10.2022
 TIME OF ACCIDENT : 09:20 HRS

10	FRONT VIDEO CAMERA <i>abe m</i>	1	\$ 580.00	\$ 580.00
			TOTAL	\$ 1,820.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD , CUT, ADJUST, KNOCK	\$ 1,800.00	800.
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,400.00	1000
3	TO SPRAY TUFF COAT	\$ 250.00	80
4	WIRING, BULB CHECKING	\$ 80.00	30
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	x
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	80
7	REFOCUS HEADLAMP BEAM	\$ 60.00	x
8	REMOVE AND REFIX AIRCON BLOWER, COOLING COIL AND REFILL AIRCON GAS	\$ 150.00	✓
9	REMOVE AND REINSTALL DASHBOARD	\$ 650.00	220
10	TRANSFER FRONT DOOR MECHANISM LH	\$ 80.00	x
11	REMOVE AND REFIX DOOR WINDOW GLASS	\$ 80.00	x
12	REMOVE AND REFIX CABIN	\$ 1,200.00	x.
13	REMOVE AND REFIX VIDEO SYSTEM	\$ 500.00	120 150
14	REMOVE AND REFIX AND RESET AUDIO SYSTEM	\$ 120.00	x
15	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	✓

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBJ1077X**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 05.10.2022
 TIME OF ACCIDENT : 09:20 HRS

16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 7,000.00

2630

Adrian Lj
 H/s 06/10/22

09 Days.

ESTIMATE REPORT

TOTAL PARTS COST : \$ 26,808.95
 TOTAL LABOUR COST : \$ 7,000.00
 TOTAL REPAIR COST : \$ 33,808.95

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 14741.35
 H/s: 11.8K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: