

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC22010044/Gnce2	
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	11-11-2022 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKC 5133X	Veh. Ir	spected	SHA 1401U
	Policy No.		Covera	age (\$)	0.00
	Claim No.	MT/1195347-001	Exces	s (\$)	0.00
	Assign From		Assigr	n Date	10/10/2022
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AE IONIQ HEV 1.6	c.c		1580
	Engine No.	HIDDEN	Year o	f Reg.	2019
	Chassis No.	KMHC851CVLU190197	Colou	•	BLUE
	Odometer	369506	Steering		IN ORDER
	Brakes	IN ORDER	Modifi	cation	NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	WEST		6 mm
	L/H Front Tyre	195/65 R15	WEST		6 mm
	R/H Rear Tyre	195/65 R15	WEST		6 mm
	L/H Rear Tyre	195/65 R15	WEST		6 mm
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	07/10/2022	•	tion Date	10/10/2022
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD  59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				