COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Model

Vehicle No.: SHA8755C Make

: HYUNDAI

: 1-40

Date: 10/10/2022

Insurance: INCOME

MVA: MS. LOKE Y Y

Parts Description / Labour	Туре	Unit Price	1	Amount	
REAR BUMPER COVER / CAA	A CONTRACTOR OF THE		\$	553.00	
REAR BUMPER CLIPS			\$	22.00	
REAR BUMPER LOWER COVER X			\$	228.00	
REAR BUMPER REINFORCEMENT 1			\$	428.40	1 x
SUB TOTAL			\$	1,231.40	
LESS 20%			\$	246.28	
DISCOUNTED TOTAL			\$	985.12	-
REAR BUMPER REVERSE SENSOR X			\$	135.70	Nett
			\$	135.70	Nett
Labour Charge					
PANEL BEATING			\$	300.00	12
SPRAY PAINTING CHARGE			\$	300.00	7
REMOVE/REFIX REVERSE SENSOR			\$	60.00	7
TOTAL LABOUR			\$	660.00	,
ESTIMATE TOTAL			\$	1,780.82	
	REAR BUMPER COVER REAR BUMPER CLIPS REAR BUMPER LOWER COVER REAR BUMPER REINFORCEMENT SUB TOTAL LESS 20% DISCOUNTED TOTAL REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE REMOVE/REFIX REVERSE SENSOR TOTAL LABOUR	REAR BUMPER COVER REAR BUMPER LOWER COVER REAR BUMPER LOWER COVER REAR BUMPER REINFORCEMENT SUB TOTAL LESS 20% DISCOUNTED TOTAL REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE REMOVE/REFIX REVERSE SENSOR TOTAL LABOUR	REAR BUMPER COVER REAR BUMPER LOWER COVER REAR BUMPER LOWER COVER REAR BUMPER REINFORCEMENT SUB TOTAL LESS 20% DISCOUNTED TOTAL REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE REMOVE/REFIX REVERSE SENSOR TOTAL LABOUR	REAR BUMPER COVER REAR BUMPER CLIPS REAR BUMPER LOWER COVER REAR BUMPER REINFORCEMENT SUB TOTAL LESS 20% DISCOUNTED TOTAL REAR BUMPER REVERSE SENSOR Labour Charge PANEL BEATING SPRAY PAINTING CHARGE REMOVE/REFIX REVERSE SENSOR TOTAL LABOUR \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	S

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Pays. 45 600 Ex (o) 10 2 pm

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting To display damaged part(s) during resurvey Supplement era re riveyed and is subject **Acknowledged** Signature: Date: