

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22010055/GWY3Q2**Date:** 16/12/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ000651		
Claimant Vehicle No :	SHD4443M	Insured Vehicle No :	SJA699K		
Date of Loss:	11/10/2022	Nature of Claim:	TP	Claim No:	M2205660

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4443M	Engine No:	G4LEJU112140
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU115233
Reg. Date:	08/11/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,142.72	996.12	1,146.60	53.51
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	640.00	180.00	21.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,973.72	1,647.12	1,326.60	44.61
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,973.72	1,300.00	1,673.72	56.28
+ GST 7.00/7.00% (S\$)	208.16	91.00	117.16	56.28
Nett Amount (S\$)	3,181.88	1,391.00	1,790.88	56.28

INSPECTION

Date of Assignment:	12/10/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	12/10/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Dec 2022)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD4443M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
3	1		*REAR BUMPER LOWER MOULDING	Not Necessary	155.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL
5	2		*REAR BUMPER REINFORCEMENT BRKT RH / LH	Serviceable	276.20 FL	*- FL
6	1		*REAR BUMPER REFLECTOR RH / LH	Not Necessary	41.45 FL	*- FL
7	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
8	1		*REAR BUMPER FOGLAMP	Not Necessary	201.50 FL	*- FL
9	1		*REAR SMART KEY ANTENNA	Not Necessary	40.50 FL	*- FL
10	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
11	1		*REVERSE SENSORS	Not Necessary	180.00 F	*- F
12	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	*- FL
13	2		*REAR FENDER ADVERTISEMENT STICKER RH / LH	Necessary	200.00 F	*200.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,570.90	1,182.65
- List Item Discount on L Items 20.00/20.00% (\$)	428.18	186.53
Total Parts (\$)	2,142.72	996.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	40.00
Gross Labour Cost (\$\$)			820.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >