

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010058/UPA3Q2**Date:** 18/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800001871
Claimant Vehicle No :	SJH3542Y	Insured Vehicle No :	SKK3283S
Date of Loss:	11/10/2022	Nature of Claim:	TP
		Claim No:	5260316258SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH3542Y	Engine No:	1ZZ3112660
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12W003000100
Reg. Date:	01/08/2008 (Man. Year: 2008)	Odometer:	163853 km
Colour:	Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,857.30	4,985.02	5,872.28	54.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	1,990.00	2,710.00	57.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,557.30	6,975.02	8,582.28	55.17
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	15,557.30	5,500.00	10,057.30	64.65
+ GST 7.00/7.00% (S\$)	1,089.01	385.00	704.01	64.65
Nett Amount (S\$)	16,646.31	5,885.00	10,761.31	64.65
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,387.00		
Global Sum Settlement (S\$)		6,380.00		

INSPECTION

Date of Assignment:	12/10/2022		
Date Inspected:	12/10/2022	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,288.10 FL	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	145.40 FL	*145.40 FL
3	1		*TAILGATE	Badly Dented	1,742.00 FL	*1,485.10 FL
4	1		*TAILGATE OUTER HANDLE	Bent / Cracked	299.40 FL	*299.40 FL
5	1		*TAILGATE AERO TOURER EMBLEM	Necessary	364.80 FL	*68.00 FL
6	1		*TAILGATE INNER LOCK	Dented / Damaged	616.80 FL	*409.20 FL
7	1		*TAILGATE WEATHERSTRIP	Twisted	386.20 FL	*386.20 FL
8	1		*TAILGATE INNER TRIM BOARD	Not Necessary	567.30 FL	*- FL
9	1		*REAR BUMPER	Dented / Deformed	665.90 FL	*485.10 FL
10	1		*REAR BUMPER DAMPERS	N/S Dented	170.00 FL	*85.00 FL
11	2		*REAR BUMPER SIDE RETAINERS	Bent	130.00 FL	*130.00 FL
12	2		*REAR BUMPER REFLECTORS	Not Necessary	120.00 FL	*- FL
13	1		*REAR END PANEL OUTER	Badly Dented	842.00 FL	*545.10 FL
14	1		*REAR END PANEL TOP GARNISH	Twisted	381.80 FL	*288.20 FL
15	2		*TAILLAMPS	Cracked	1,190.00 FL	*960.00 FL
16	1		*REAR FENDER INNER TRIM BOARD O/S	Not Necessary	645.20 FL	*- FL
17	1		*REAR FENDER UNDER SHIELD O/S	Not Necessary	121.50 FL	*- FL
18	1		*REAR FLOOR PANEL	Repair	1,410.80 FL	*- FL
19	1		*REAR END PANEL LOWER	Not Necessary	389.20 FL	*- FL
20	1		*REAR LICENCE PLATE	Serviceable	50.00 FS	*- FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
23	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
24	1		*TAILGATE BORNEO LOGO	Necessary	60.00 FS	*40.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
27	1		*SET REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
28	1		*REAR BUMPER LOWER SPOILER	Deformed / Cracked	1,000.00 FS	*600.00 FS
29	1		*SET REAR FENDER UNDER SHIELD CLIPS O/S	Not Necessary	30.00 FS	*- FS
30	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,726.40	6,306.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,869.10	1,321.68
Total Parts (\$\$)	10,857.30	4,985.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REMOVE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REFIX TAILGATE MECHANISM	New	100.00	60.00
5	TO REMOVE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO REMOVE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO REMOVE & REFIX FUEL TANK	New	100.00	0.00
8	TO REMOVE & REFIX REAR REVERSE CAMERA	New	100.00	0.00
9	TO SPRAY ANTI-RUST PROOFING	New	120.00	60.00
10	TO DIAGNSIS & REPROGRAMME SYSTEM	New	180.00	0.00
11	LABOUR FOR PANEL BEATING	New	1,800.00	600.00
12	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,000.00
			Gross Labour Cost (S\$)	4,700.00
				1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >