

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22010067/EQY3E2**Date:** 06/12/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMV9935Z**Insured Vehicle No :** GBM9991M

Date of Loss: 04/10/2022

Nature of Claim: TP

Claim No: CDMCG22002057

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMV9935Z**

Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI (A)

Engine No: CZDA53794

Reg. Date: 29/10/2020 (Man. Year: 2019)

Chassis No: WVGZZZ1TZKW072656

Colour: White

Odometer: 30832 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R16

Rear Tyre Size: 215/50 R16

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,619.19	10,068.95	2,550.24	20.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,830.00	9,390.00	7,440.00	44.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,449.19	19,458.95	9,990.24	33.92
+ GST 7.00/7.00% (S\$)	2,061.44	1,362.13	699.31	33.92
Nett Amount (S\$)	31,510.63	20,821.08	10,689.55	33.92

INSPECTION

Date of Assignment: 12/10/2022

Date Inspected: 13/10/2022

Inspected At:

Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2022)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV9935Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*1K WINDOW ADHESIVE	Necessary	102.88 FS	*102.88 FS
2	1		*ALL PURPOSE CLEANER	Necessary	102.88 FS	*102.88 FS
3	1		*PRIMER	Necessary	30.27 FS	*30.27 FS
4	1		*ACTIVATOR	Necessary	26.27 FS	*26.27 FS
5	2		*APPLICATOR	Necessary	22.32 FS	*22.32 FS
6	1		*REAR TRUNK LID	Dented	2,788.77 FS	*2,788.77 FS
7	1		*SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM LH	Necessary	304.32 FS	*304.32 FS
8	1		*SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM RH	Cut	309.67 FS	*309.67 FS
9	1		*PACKING ADHESIVE RR NUMBER PLATE PACKING	Necessary	32.91 FS	*32.91 FS
10	4		*RIVETTED CAP NUT	Necessary	10.56 FS	*10.56 FS
11	1		*HOOD LATCH BOOT LID LOCK	Not Necessary	192.96 FS	*- FS
12	1		*VW SIGN BLACK / BRIGHT CHRO	Necessary	117.06 FS	*117.06 FS
13	1		*INSCRIPTION BRIGHT CHROME NAME PLATE - TOURAN	Necessary	80.37 FS	*80.37 FS
14	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRALELIGHT	Necessary	245.82 FS	*245.82 FS
15	1		*TAILLIGHT WITH BACK-UP LI RHS TAILLIGHT INNER	Broken	287.30 FS	*287.30 FS
16	1		*TAILLIGHT WITH BACK-UP LI RHS TAILLIGHT OUTER	Broken	344.61 FS	*344.61 FS
17	2		*MOUNTING	Necessary	0.98 FS	*0.98 FS
18	1		*ATTACHMENT ELEMENT BOLT	Necessary	11.62 FS	*11.62 FS
19	1		*GAS-FILLED STRUT RHS BOOT LID ABSORBER	Not Necessary	132.95 FS	*- FS
20	2		*PLUG	Necessary	10.34 FS	*10.34 FS
21	1		*BUFFER ADJUSTABLE	Necessary	17.40 FS	*17.40 FS
22	1		*GASKET BOOT LID WEATHERSTRIP	Not Necessary	346.72 FS	*- FS
23	1		*COVER FOR BUMPER PRIMED	Dented	1,537.14 FS	*1,537.14 FS
24	1		*SPOILER SATIN BLACK	Not Necessary	368.79 FS	*- FS
25	1		*BUMPER REINFORCEMENT	Not Necessary	682.38 FS	*- FS
26	7		*BOLT HEX. HD. WITH SHOULD	Necessary	31.08 FS	*31.08 FS
27	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	72.88 FS	*- FS
28	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	49.88 FS	*- FS
29	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Broken	49.88 FS	*49.88 FS
30	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	40.61 FS	*- FS
31	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Broken	40.61 FS	*42.04 FS
32	1		*REFLECTOR RHS REFLECTOR OUTER	Not Necessary	75.79 FS	*- FS
33	1		*REFLECTOR RHS REFLECTOR INNER	Not Necessary	75.79 FS	*- FS
34	1		*SIDE WINDOW NOT PRE-TREAT RHR FENDER GLASS	Necessary	441.08 FS	*441.08 FS
35	1		*1K WINDOW ADHESIVE	Necessary	51.44 FS	*51.44 FS
36	1		*PRIMER	Necessary	30.27 FS	*30.27 FS
37	1		*ACTIVATOR	Necessary	26.27 FS	*26.27 FS
38	2		*APPLICATOR	Necessary	22.32 FS	*22.32 FS
39	1		*SECTIONAL PART SIDE PANEL RHR FENDER	Dented	2,155.11 FS	*2,155.11 FS
40	1		*2K-INSERT FOAM	Necessary	163.23 FS	*163.23 FS
41	1		*SEALANT CAN BE SPRAYED	Necessary	66.78 FS	*66.78 FS
42	1		*ZINC SPRAY	Necessary	72.86 FS	*72.86 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*2K-BODY ADHESIVE	Necessary	469.52 FS	*469.52 FS
44	1		*UNDERSEAL	Necessary	15.50 FS	*15.50 FS
45	1		*WHEELHOUSE PROTECTOR RHR FENDER LINER	Not Necessary	229.65 FS	*- FS
46	1		*FUEL FILLER DOOR WITH HOU	Not Necessary	225.19 FS	*- FS
47	1		*TIRE PRESSURE LABEL	Not Necessary	15.15 FS	*- FS
48	1		*STONE PROTECTION FOIL RHR FENDER FOIL	Necessary	35.98 FS	*35.98 FS
49	1		*VENT TRIM RHR FENDER AIR DUCT	Not Necessary	42.93 FS	*- FS
50	5		*EXPANDING NUT	Necessary	12.10 FS	*12.10 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	12,619.19 10,068.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	6,720.00	4,200.00
4	SPRAY PAINT	New	4,800.00	2,400.00
5	R&R REAR W/SCREEN	New	840.00	840.00
6	R&R RHS REAR FENDER GLASS	New	840.00	420.00
7	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
8	R&R REAR SEAT	New	840.00	0.00
9	R&R REAR LUGGAGE TRIM	New	840.00	0.00
10	REAR WATER LEAK TEST	New	150.00	150.00
11	RHR FENDER GLASS SOLAR FILM	New	200.00	200.00
Gross Labour Cost (S\$)			16,830.00	9,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >