

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010069/UPA3Q2**Date:** 24/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700024564
Claimant Vehicle No :	SJL4652K	Insured Vehicle No :	SLB1181B
Date of Loss:	10/10/2022	Nature of Claim:	TP
		Claim No:	9784824954SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL4652K	Engine No:	R18A12805105
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN68408S205103
Reg. Date:	27/11/2008 (Man. Year: 2008)	Odometer:	335119 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Tourador 5 mm	Rear Left Side:	Tourador 5 mm
Front Right Side:	Tourador 5 mm	Rear Right Side:	Tourador 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,844.36	801.12	2,043.24	71.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	840.00	1,920.00	69.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,604.36	1,641.12	3,963.24	70.72
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	5,604.36	1,300.00	4,304.36	76.80
+ GST 7.00/7.00% (S\$)	392.31	91.00	301.31	76.80
Nett Amount (S\$)	5,996.67	1,391.00	4,605.67	76.80
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
Nett Liability (S\$)		1,591.00		

INSPECTION

Date of Assignment:	12/10/2022		
Date Inspected:	12/10/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	991.10 FL	*- FL
2	1		*TAILGATE LOCK	Not Necessary	124.50 FL	*- FL
3	1		*TAILGATE LOWER LOCK	Not Necessary	207.70 FL	*- FL
4	1		*TAILGATE RUBBER	Not Necessary	145.50 FL	*- FL
5	1		*TAILGATE HONDA LOGO (STEAM)	Necessary	36.00 FL	*36.00 FL
6	1		*TAILGATE INNER TRIM BOARD	Not Necessary	170.30 FL	*- FL
7	1		*REAR BUMPER	Dented / Deformed	704.90 FL	*665.40 FL
8	1		*REAR BUMPER TOWING COVER	Not Necessary	14.80 FL	*- FL
9	1		*REAR W/S MOULDING	Not Necessary	27.70 FL	*- FL
10	1		*EXHAUST MUFFLER CHROME PIPE	Not Necessary	121.80 FL	*- FL
11	1		*REAR END PANEL	Repair	346.20 FL	*- FL
12	1		*REAR END PANEL GARNISH	Not Necessary	141.20 FL	*- FL
13	10		*REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
14	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS
15	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
16	2		*SET SEALANT	Not Necessary	80.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,466.70	941.40
- List Item Discount on L Items 20.00/20.00% (S\$)	622.34	140.28
Total Parts (S\$)	2,844.36	801.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX SEATS GARNISH ,ETC	New	120.00	0.00
2	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
3	REMOVE AND REFIX REAR SENSOR	New	80.00	50.00
4	TUFF COAT	New	120.00	0.00
5	WIRING CHECK	New	120.00	20.00
6	LABOUR CHARGE	New	1,200.00	320.00
7	SPRAY PAINTING (REAR)	New	1,000.00	450.00
Gross Labour Cost (\$\$)			2,760.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >