

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010077/EWCE2**Date:** 03/01/2023**REFERENCE**

Insured/Claimant:	CHONG LEE FONG	Policy No:	1800080001	
Date of Loss:	08/10/2022	Nature of Claim:	OD	Claim No: 6687657894SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9963M		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK064081
Reg. Date:	20/07/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF49JN015027
Colour:	Grey	Odometer:	61333 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,923.12	24,498.88	12,424.24	33.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,372.00	7,322.00	4,050.00	35.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,295.12	31,820.88	16,474.24	34.11
- Excess (S\$)	1,300.00	1,300.00	0.00	0.00
(S\$)	46,995.12	30,520.88	16,474.24	35.06
+ GST 7.00/7.00% (S\$)	3,289.66	2,136.46	1,153.20	35.06
Nett Amount (S\$)	50,284.78	32,657.34	17,627.44	35.06

INSPECTION

Date of Assignment:	12/10/2022		
Date Inspected:	12/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: CHEN TSUE YEE**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
4	1		*RADIATOR GRILLE	Broken	1,478.00 FS	*1,182.40 FS
5	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	531.00 FS	*- FS
6	4		*FRONT PARKING AID SEAL RING	Necessary	10.00 FS	*8.00 FS
7	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	139.00 FS	*110.80 FS
8	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
9	2		*FRONT REINFORCEMENT BEAM SUPPORT - LH / RH	Broken	64.00 FS	*51.04 FS
10	1		*FRONT BUMPER BRACKET - CENTER	Broken	154.00 FS	*122.80 FS
11	2		*FRONT REINFORCEMENT BEAM BRACKET - LH / RH	Not Necessary	508.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Broken	143.00 FS	*114.00 FS
13	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
14	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
15	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
16	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
17	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
18	2		*BONNET HINGE - LH / RH	Not Necessary	680.00 FS	*- FS
19	2		*BONNET STRIKER - LH / RH	Not Necessary	112.00 FS	*- FS
20	2		*BONNET LOCK - LH / RH	Not Necessary	455.00 FS	*- FS
21	1		*BONNET BOWDEN CABLE - CENTER	Bent	64.00 FS	*50.56 FS
22	1		*BONNET RELEASE CABLE	Distorted	64.00 FS	*50.56 FS
23	2		*HEADLIGHT - LH / RH	Broken	16,588.00 FS	*13,270.40 FS
24	1		*LOCK CARRIER	Broken	1,478.00 FS	*901.60 FS
25	1		*RADIATOR AIR GUIDE - LH INNER	Broken	32.00 FS	*25.60 FS
26	1		*RADIATOR AIR GUIDE - LH OUTER	Broken	14.00 FS	*10.88 FS
27	1		*RADIATOR AIR GUIDE - RH INNER	Broken	32.00 FS	*25.60 FS
28	1		*RADIATOR AIR GUIDE - RH OUTER	Broken	14.00 FS	*10.88 FS
29	1		*RADIATOR AIR GUIDE - CENTER	Not Necessary	19.00 FS	*- FS
30	1		*CHARGE AIR COOLER	Not Necessary	654.00 FS	*- FS
31	1		*A/C CONDENSER	Dented	683.00 FS	*546.00 FS
32	1		*A/C CONDENSER O-RING	Not Necessary	13.00 FS	*- FS
33	1		*A/C CONDENSOR SEAL RING	Distorted	12.00 FS	*9.44 FS
34	1		*A/C PRESSURE SENSOR	Not Necessary	206.00 FS	*- FS
35	1		*A/C HIGH-PRESSURE SWITCH SAFETY SWITCH VALVE	Not Necessary	53.00 FS	*- FS
36	1		*RADIATOR	Bent	1,013.00 FS	*810.40 FS
37	4		*READY-MIX COOLANT	Necessary	237.12 FS	*237.12 FS
38	1		*RADIATOR FAN RING	Not Necessary	292.00 FS	*- FS
39	1		*RADIATOR FAN CONTROL UNIT	Bent	2,489.00 FS	*1,991.20 FS
40	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
41	1		*SUNDRIES	Necessary	400.00 FS	*55.36 FS
42	1		*AIR GUIDE GRILLE - RH (Supplementary)	Cut	151.00 FS	*120.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **36,923.12** **24,498.88**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH FRONT HEADLIGHTS CONTROL UNIT AND POWER MODULES	New	700.00	500.00
3	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
4	TO DISMANTLE FRONT BUMPER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	2,500.00
5	TO RESPRAY FRONT BUMPER AND BONNET	New	1,800.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO RESPRAY BOTH FRONT FENDERS (Supplementary)	New	700.00	250.00
8	TO RESPRAY BOTH FRONT FENDERS (Supplementary)	New	2,100.00	1,100.00
Gross Labour Cost (S\$)			11,372.00	7,322.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >