

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010090/KCY3M4**Date:** 05/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00155002100
Claimant Vehicle No :	SLH144J	Insured Vehicle No :	XE6919A
Date of Loss:	08/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207262/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH144J	Engine No:	30219660B37C15A
Make & Model:	BMW 216D, 1.5 (A)	Chassis No:	WBA2E320005B45406
Reg. Date:	21/10/2016 (Man. Year: 2016)	Odometer:	133187 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,810.20	6,414.13	9,396.07	59.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,020.00	2,180.00	68.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,010.20	7,434.13	11,576.07	60.89
Approved Total (Overridden) (\$\$)		5,900.00		
(\$\$)	19,010.20	5,900.00	13,110.20	68.96
+ GST 7.00/7.00% (\$\$)	1,330.71	413.00	917.71	68.96
Nett Amount (\$\$)	20,340.91	6,313.00	14,027.91	68.96

INSPECTION

Date of Assignment:	11/10/2022	
Date Inspected:	12/10/2022 Inspected At:	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2022)
Parts:	143	BMW 216D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH144J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR FILTER BOX HOSE	Cracked	205.10 F	*205.10 FL
2	1		*FRONT BUMPER	Cracked	2,200.00 F	*1,220.00 FL
3	1		*FRONT BUMPER AIR DUST CENTRE INNER	Cracked	365.10 F	*301.60 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 F	*80.00 FL
5	1		*FRONT BUMPER INNER GARNISH	Cracked	395.10 F	*395.10 FL
6	1		*FRONT BUMPER INNER IMPACT BRACKET - LH	Repair	82.10 F	*- FL
7	1		*FRONT BUMPER INNER IMPACT BRACKET - RH	Repair	82.10 F	*- FL
8	1		*FRONT BUMPER GRILLE - LH	Cracked	285.00 F	*262.00 FL
9	1		*FRONT BUMPER GRILLE - RH	Missing	285.00 F	*262.00 FL
10	1		*FRONT BUMPER LOWER GRILLE CENTRE	Serviceable	355.20 F	*- FL
11	1		*FRONT BUMPER NUMBER PLATE GARNISH	Serviceable	268.10 F	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Repair	464.00 F	*- FL
13	1		*FRONT BUMPER SIDE RETAINER - LH	Serviceable	112.00 F	*- FL
14	1		*FRONT BUMPER SIDE RETAINER - RH	Serviceable	112.00 F	*- FL
15	1		*FRONT BUMPER SPONGE	Cracked	335.10 F	*149.50 FL
16	1		*FRONT FENDER - RH	Repair	960.00 F	*- FL
17	1		*FRONT GRILLE MOULDING - LH	Dented	189.20 F	*189.20 FL
18	1		*FRONT GRILLE MOULDING - RH	Missing	189.20 F	*189.20 FL
19	1		*FRONT EMBLEM	Necessary	238.10 F	*102.00 FL
20	1		*FRONT HEADLAMP LOWER BRACKET - LH	Serviceable	95.50 F	*- FL
21	1		*FRONT HEADLAMP LOWER BRACKET - RH	Repair	95.50 F	*- FL
22	1		*FRONT SUPPORT PANEL	Cracked	985.00 F	*985.00 FL
23	1		*HEAD LAMP - LH	Serviceable	3,685.90 F	*- FL
24	1		*HEAD LAMP - RH	Broken	3,685.90 F	*2,363.65 FL
25	1		*FRONT NUMBER PLATE	Missing	60.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,810.20** **6,749.35**

- List Item Discount on L Items 0.00/5.00% (\$\$) **0.00** **335.22**

Total Parts (\$\$) **15,810.20** **6,414.13**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	New	1,200.00	600.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,200.00	400.00
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL	New	250.00	0.00
4	COMPUTER DIAGNOSTIC	New	400.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	150.00	20.00
Gross Labour Cost (\$)			3,200.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >