

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010093/UNY3Q2**Date:** 16/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00130582101
Claimant Vehicle No :	SKB3777G	Insured Vehicle No :	YQ2287R
Date of Loss:	08/10/2022	Nature of Claim: TP	Claim No: SNM22D207276/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB3777G		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 CVT (A)	Engine No:	4B12NS2168
Reg. Date:	02/12/2014 (Man. Year: 2014)	Chassis No:	JMYXTGF3WZF001063
Colour:	Silver	Odometer:	42554 km
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55Z R18	Rear Tyre Size:	225/55Z R18
Front Left Side:	Kinforest 6 mm	Rear Left Side:	Kinforest 6 mm
Front Right Side:	Kinforest 6 mm	Rear Right Side:	Kinforest 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,307.50	2,691.00	616.50	18.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,120.00	530.00	32.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,957.50	3,811.00	1,146.50	23.13
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	4,957.50	3,050.00	1,907.50	38.48
+ GST 7.00/7.00% (S\$)	347.03	213.50	133.53	38.48
Nett Amount (S\$)	5,304.53	3,263.50	2,041.03	38.48

INSPECTION

Date of Assignment:	12/10/2022		
Date Inspected:	07/11/2022	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.0 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB3777G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	981.00 FL	*981.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
3	1		*FRONT BUMPER SIDE HOLDER -LH/RH	O/S Cracked	44.00 FL	*22.00 FL
4	1		*FRONT BUMPER WHEEL OUTER ARCH SIDE GARNISH -RH	Grazed	104.00 FL	*104.00 FL
5	1		*FRONT FENDER -RH	Buckled	663.00 FL	*663.00 FL
6	1		*FRONT FENDER WHEEL OUTER ARCH GARNISH -RH	Grazed	179.00 FL	*179.00 FL
7	10		*FRONT FENDER COWLING CLIPS -RH	Necessary	50.00 FL	*50.00 FL
8	1		*HEAD LAMP -RH	Cracked	856.00 FL	*856.00 FL
9	13		*SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	65.00 FL	*- FL
10	1		*SUPPORT PANEL	Repair	206.00 FL	*- FL
11	1		*GRILLE ASSY	Not Necessary	345.00 FL	*- FL
12	1		*GRILLE LOGO	Not Necessary	47.00 FL	*- FL
13	1		*FRONT BUMPER COVER -RH	Grazed	45.00 FL	*45.00 FL
14	1		*FRONT BUMPER CHROME -RH	Cut	30.00 FL	*30.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,675.00	2,990.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	367.50	299.00
Total Parts (\$\$)	3,307.50	2,691.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,FRONT BONNET ,RH HEADLAMP PANEL ,TOP SUPPORT PANEL ,REMOVE ,REPLACE ACCIDENT PARTS	New	600.00	500.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	900.00	600.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO RESET CHECKLIGHT	New	100.00	0.00
Gross Labour Cost (\$\$)			1,650.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >