

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010096/UQY3Q2**Date:** 31/10/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00131362203

Claimant Vehicle No : SKP9465T **Insured Vehicle No :** SJL9262U

Date of Loss: 10/10/2022 Nature of Claim: TP Claim No: SNM22D207299/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP9465T**

Make & Model: HONDA FREED, 1.5 G (A) Engine No: L15A6912843

Reg. Date: 24/10/2014 (Man. Year: 2014) Chassis No: GB31602813

Colour: Silver Odometer: 172946 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16

Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 12,542.20 | 7,189.12 | 5,353.08 | 42.68 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,380.00 | 2,460.00 | 1,920.00 | 43.84 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 16,922.20 | 9,649.12 | 7,273.08 | 42.98 |
| Approved Total (Overridden) (S\$) | | 7,700.00 | | |
| (S\$) | 16,922.20 | 7,700.00 | 9,222.20 | 54.50 |
| + GST 7.00/7.00% (S\$) | 1,184.55 | 539.00 | 645.55 | 54.50 |
| Nett Amount (S\$) | 18,106.75 | 8,239.00 | 9,867.75 | 54.50 |

INSPECTION

Date of Assignment: 12/10/2022

Date Inspected: 12/10/2022 Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines)
Blk 9006 #01-200 Tampines St 93
Singapore

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 31 Oct 2022) |
| Parts: M1-MPV | HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SKP9465T) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|------------------------------|-------------|--------------|
| 1 | 1 | | *TAILGATE GLASS MOULDING | Necessary | 225.00 FL | *148.10 FL |
| 2 | 1 | | *TAILGATE | Badly Dented | 1,495.00 FL | *1,288.10 FL |
| 3 | 1 | | *TAILGATE LOGO | Necessary | 65.00 FL | *65.00 FL |
| 4 | 1 | | *TAILGATE EMBLEM -FREED | Necessary | 85.00 FL | *85.00 FL |
| 5 | 1 | | *TAILGATE GARNISH CHROME MOULDING | Cracked | 480.00 FL | *266.50 FL |
| 6 | 2 | | *REAR NUMBER PLATE LAMP | Not Necessary | 178.00 FL | *- FL |
| 7 | 1 | | *TAILGATE OUTER HANDLE WITH SENSOR | Shorted | 125.00 FL | *125.00 FL |
| 8 | 1 | | *TAILGATE LOCK /UNLOCK SENSOR OUTER | Shorted | 165.00 FL | *165.00 FL |
| 9 | 1 | | *TAILGATE STOPPER | O/S Not Necessary / N/S Torn | 60.00 FL | *20.00 FL |
| 10 | 1 | | *TAILGATE WEATHERSTRIP | Twisted | 225.00 FL | *225.00 FL |
| 11 | 1 | | *TAILGATE INNER TRIM BOARD | Deformed / Torn | 480.00 FL | *366.10 FL |
| 12 | 1 | | *TAILGATE INNER TRIM BOARD SMALL COVER | Twisted | 55.00 FL | *30.00 FL |
| 13 | 1 | | *TAILGATE LOCK | Dented / Jammed | 305.00 FL | *305.00 FL |
| 14 | 1 | | *TAILGATE LOCK STRIKER | Not Necessary | 95.00 FL | *- FL |
| 15 | 1 | | *TAILLAMP | N/S Cracked | 1,186.00 FL | *593.00 FL |
| 16 | 1 | | *REAR BUMPER | Distorted | 1,050.00 FL | *845.10 FL |
| 17 | 1 | | *SET REAR BUMPER GROMET | Necessary | 50.00 FL | *50.00 FL |
| 18 | 2 | | *REAR BUMPER SIDE RETAINER | Bent | 96.00 FL | *96.00 FL |
| 19 | 1 | | *REAR BUMPER TOW HOOK COVER | Not Necessary | 55.00 FL | *- FL |
| 20 | 1 | | *TAILGATE BUZZER | Cracked | 105.00 FL | *105.00 FL |
| 21 | 1 | | *EXHAUST MUFFLER | Repair | 850.00 FL | *- FL |
| 22 | 2 | | *EXHAUST MUFFLER RUBBER HANGER | Not Necessary | 78.00 FL | *- FL |
| 23 | 1 | | *REAR END PANEL -OUTER | Badly Dented | 580.00 FL | *580.00 FL |
| 24 | 1 | | *REAR END PANEL GARNISH-TOP | Twisted | 135.00 FL | *135.00 FL |
| 25 | 2 | | *REAR FENDER INNER TRIM | Deformed / Torn | 960.00 FL | *960.00 FL |
| 26 | 1 | | *REAR INNER CARPET | Torn | 1,780.00 FL | *850.00 FL |
| 27 | 1 | | *REAR BUMPER TOP BEAM | No such part | 145.00 FL | *- FL |
| 28 | 2 | | *TAILGATE HINGES | Not Necessary | 308.00 FL | *- FL |
| 29 | 1 | | *TAILGATE INNER HANDLE | Shorted | 98.00 FL | *98.00 FL |
| 30 | 1 | | *REAR WIPER LINKAGE | Not Necessary | 354.00 FL | *- FL |
| 31 | 1 | | *REAR WIPER MOTOR | Bent / Jammed | 498.00 FL | *498.00 FL |
| 32 | 1 | | *REAR COMPARTMENT PANEL | Repair | 978.00 FL | *- FL |
| 33 | 1 | | *REAR COMPARTMENT BOARD | No such part | 465.00 FL | *- FL |
| 34 | 1 | | *TAILGATE GLASS INNER SEAL | Necessary | 100.00 FS | *40.00 FS |
| 35 | 1 | | *TAILGATE GLASS SEALANT | Necessary | 40.00 FS | *40.00 FS |
| 36 | 1 | | *SET TAILGATE GARNISH CLIP | Not Necessary | 50.00 FS | *- FS |
| 37 | 1 | | *SET REVERSE CAMERA | Shorted | 400.00 FS | *300.00 FS |
| 38 | 1 | | *REAR NUMBER PLATE | Bent | 45.00 FS | *40.00 FS |
| 39 | 1 | | *SET TAILGATE INNER TRIM BOARD CLIPS | Necessary | 50.00 FS | *50.00 FS |
| 40 | 1 | | *SET REAR BUMPER CLIP | Necessary | 50.00 FS | *50.00 FS |
| 41 | 1 | | *SET REVERSE SENSOR | Shorted | 250.00 FS | *200.00 FS |
| 42 | 1 | | *SET REAR END PANEL GARNISH CLIP | Not Necessary | 50.00 FS | *- FS |
| 43 | 1 | | *SET REAR FENDER INNER TRIM CLIP | Not Necessary | 60.00 FS | *- FS |
| 44 | 1 | | *TAILGATE SEALANT | Necessary | 100.00 FS | *50.00 FS |
| 45 | 1 | | *REAR COMPARTMENT RUBBER INSULATOR | Necessary | 300.00 FS | *100.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|-------------|-----------|---|------------------|-----------------|
| | | | | | Sub Total (S\$) | 15,304.00 | 8,768.90 |
| | | | | | - List Item Discount on L Items 20.00/20.00% (S\$) | 2,761.80 | 1,579.78 |
| | | | | | Total Parts (S\$) | 12,542.20 | 7,189.12 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO TRANSFER TAILGATE GLASS | New | 150.00 | 120.00 |
| 2 | TO TRANSFER TAILGATE MECHANISMS | New | 150.00 | 60.00 |
| 3 | RE-SPRAY ANTI-RUST | New | 150.00 | 80.00 |
| 4 | APPLY BODY SEALANT TO CAR JOINTS | New | 150.00 | 50.00 |
| 5 | INSTALL REVERSE SENSOR } | New | 100.00 | 50.00 |
| 6 | INSTALL REVERSE CAMERA } | New | 150.00 | 0.00 |
| 7 | TO CHECK LIGHT AND WIRING | New | 50.00 | 20.00 |
| 8 | TO REMOVE INNER TRIM , GARNISH ,ETC TO FACILITATE REPAIR AND TO FIX BACK | New | 200.00 | 80.00 |
| 9 | TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL ,REPAIR INNER PANEL ,REWELD INNER PANEL ,REPLACE ACCIDENT DAMAGE PARTS AND ALIGN THE SAME | New | 1,400.00 | 1,000.00 |
| 10 | TO PUTTY AND RESPRAY ACCIDENT DAMAGED ARES | New | 1,400.00 | 1,000.00 |
| 11 | TO INSTALL SOLAR FILM ON REAR WINDSCREEN | New | 200.00 | 0.00 |
| 12 | TO REPLACE REAR EXHAUST AND ALIGN | New | 280.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 4,380.00 | 2,460.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >