3/7/23, 1:02 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22010099/GPA3Q2

Date: 07/03/2023

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900017709

Claimant Vehicle STACAGOR Insurance Pte. Ltd. Policy No: 1900017709

No: SFA6188B Insured Vehicle No: SMJ6719P

Date of Loss: 07/10/2022 Nature of Claim: TP Claim No: 1945101973SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFA6188B

Make & Model: AUDI A4, 1.4 (A) Engine No: CVN020553

Reg. Date: 24/10/2016 (Man. Year: 2016) Chassis No: WAUZZZF43HA047070

Colour: Brown Odometer: 133000 km

Engine Capacity: 1395 cc Market Value/New Car N/Δ

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm
Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------|----------------------|------------|------------|--------|
| Parts | | 19,068.00 | 6,476.80 | 12,591.20 | 66.03 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 9,432.00 | 2,932.00 | 6,500.00 | 68.91 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Gross Total (S\$) | 28,500.00 | 9,408.80 | 19,091.20 | 66.99 |
| | + GST 8.00/8.00% (S\$) | 2,280.00 | 752.70 | 1,527.30 | 66.99 |
| | Nett Amount (S\$) | 30,780.00 | 10,161.50 | 20,618.50 | 66.99 |
| | + Loss of Use (4.0 x | S\$60.00/day) (S\$) | 240.00 | | |
| | + Do | c/Search Fee (S\$) | 2.00 | | |
| | | Nett Liability (S\$) | 10,403.50 | | |

INSPECTION

Date of Assignment: 18/10/2022

Premium Automobiles Pte Ltd (HQ)

Date Inspected: 18/10/2022 Inspected At: 55 UBI ROAD 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|-----------------------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 2,609.00 FS | *2,087.20 FS |
| 2 | 1 | | *REAR BUMPER FIXING PARTS | Not Necessary | 480.00 FS | *-FS |
| 3 | 1 | | *REAR BUMPER SECURING STRIP | Necessary | 249.00 FS | *198.80 FS |
| 4 | 1 | | *REAR BUMPER SPOILER | Cut | 276.00 FS | *220.80 FS |
| 5 | 1 | | *REAR BUMPER REFLECTOR-LH/RH | N/S Cut / O/S Not Necessary | 92.00 FS | *36.48 FS |
| 6 | 2 | | *REAR OUTER TAIL LIGHT -LH/RH | Not Necessary | 2,270.00 FS | *-FS |
| 7 | 2 | | *REAR OUTER TAIL LIGHT TRIM -LH/RH | Not Necessary | 68.00 FS | *-FS |
| 8 | 2 | | *REAR INNER TAIL LIGHT -LH/RH | Not Necessary | 2,270.00 FS | *-FS |
| 9 | 2 | | *REAR INNER TAIL LIGHT TRIM -LH/RH | Not Necessary | 68.00 FS | *-FS |
| 10 | 2 | | *REAR LICENCE PLATE LIGHT -LH/RH | Not Necessary | 128.00 FS | *-FS |
| 11 | 1 | | *REAR BUMPER REINFORCEMENT BEAM | Bent | 1,131.00 FS | *904.80 FS |
| 12 | 2 | | *REAR BUMPER IMPACT BAR GASKET -LH/RH | Not Necessary | 32.00 FS | *-FS |
| 13 | 2 | | *REAR BUMPER GUIDE SECTION -LH/RH | Not Necessary | 52.00 FS | *- FS |
| 14 | 2 | | *REAR PARKING AID SENSOR -INNER /OUTER | Not Necessary | 531.00 FS | *-FS |
| 15 | 4 | | *REAR PARKING AID SEAL RING | Necessary | 10.00 FS | *8.00 FS |
| 16 | 1 | | *REAR LID | Buckled | 3,497.00 FS | *2,797.60 FS |
| 17 | 2 | | *REAR LID HINGE -LH/RH | Not Necessary | 510.00 FS | *- FS |
| 18 | 1 | | *REAR LID LOCK | Not Necessary | 218.00 FS | *- FS |
| 19 | 1 | | *REAR LID LOCK COVER | Not Necessary | 8.00 FS | *-FS |
| 20 | 1 | | *REAR LID ATTACHMENT PARTS | Not Necessary | 429.00 FS | *- FS |
| 21 | 1 | | *REAR LID LOCK ACTUATOR PUSH BUTTON | Not Necessary | 1,478.00 FS | *- FS |
| 22 | 1 | | *REAR LID LOCK STRIKER | Not Necessary | 37.00 FS | *- FS |
| 23 | 1 | | *REAR LID FLAP GASKET | Not Necessary | 229.00 FS | *-FS |
| 24 | 1 | | *PACKING ADHESIVE | Necessary | 21.00 FS | *16.80 FS |
| 25 | 1 | | *AUDI EMBLEM | Necessary | 144.00 FS | *114.80 FS |
| 26 | 1 | | *REAR CROSS PANEL | Not Necessary | 274.00 FS | *-FS |
| 27 | 1 | | *REAR CROSS PANEL REINFORCEMENT | Not Necessary | 532.00 FS | *- FS |
| 28 | 1 | | *REAR CROSS PANEL TRIM | Not Necessary | 185.00 FS | *-FS |
| 29 | 1 | | *REAR NO PLATE | Bent | 60.00 FS | *60.00 FS |
| 30 | 1 | | *ACRYLIC SEALANT | Not Necessary | 180.00 FS | *-FS |
| 31 | 1 | | *CAVITY WAX | Not Necessary | 140.00 FS | *- FS |
| 32 | 1 | | *STONE CHIP | Not Necessary | 180.00 FS | *- FS |
| 33 | 1 | | *METAL FILLER POWDER | Not Necessary | 280.00 FS | *- FS |
| 34 | 1 | | *SUNDRIES | Necessary | 400.00 FS | *31.52 FS |
| | | | | - | | |

F=Franchise part. S=SpcNett.

Total Parts (S\$) 19,068.00 6,476.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|--|------------|------------|----------|
| <u>Lab</u> | our Items | | | |
| 1 | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION | New | 360.00 | 360.00 |
| 2 | TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS | New | 280.00 | 280.00 |
| 3 | TO DISLODGE & REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY | New | 1,400.00 | 0.00 |
| 4 | TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID TO CUT OUT AND WELD REAR END PANELLING .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED | . New | 4,200.00 | 1,000.00 |
| 5 | TO RESPRAY REAR BUMPER ,REAR LID ,HINGES AND REAR END PANELLING | New | 3,000.00 | 1,100.00 |
| 6 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| | Gross Labou | 9,432.00 | 2,932.00 | |
| | Report was unsubmitted during this | print-out. | | |

< END OF ESTIMATES >