

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22010101/AVY3Q2**Date:** 23/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00008152201

**Claimant Vehicle  
No :** SJR4259G**Insured  
Vehicle No :** SLU5118J

Date of Loss: 01/10/2022

Nature of Claim: TP

Claim  
No: SNM22D207271/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJR4259G**

Make &amp; Model: MITSUBISHI LANCER, 1.5 (A)

Engine No: 4A910126235

Reg. Date: 24/06/2009 (Man. Year: 2009)

Chassis No: JMYSRCY2A9U004290

Colour: Red

Odometer: 130179 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,420.92	1,289.60	2,131.32	62.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	650.00	1,500.00	69.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,570.92</b>	<b>1,939.60</b>	<b>3,631.32</b>	<b>65.18</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,570.92</b>	<b>1,500.00</b>	<b>4,070.92</b>	<b>73.07</b>

**INSPECTION**

Date of Assignment: 27/10/2022

Date Inspected: 25/10/2022 Inspected At:

Hua Meng Spray Painting Workshop (HQ)  
No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki  
Bukit  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
<b>Parts:</b>	143	mitsubishi LANCER 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJR4259G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Repair	690.80 FL	*- FL
2	1		*REAR BUMPER	Deformed	1,620.00 FS	*850.00 FS
3	1		*REAR BUMPER SIDE HOLDER	O/S Necessary	88.00 FL	*44.00 FL
4	1		*REAR RH SPORT RIM	Cut	800.00 FS	*400.00 FS
5	1		*REAR RH TYRE	Not Necessary	300.00 FS	*- FS
					<b>Sub Total (\$)</b>	<b>3,498.80 1,294.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	<b>77.88 4.40</b>
					<b>Total Parts (\$)</b>	<b>3,420.92 1,289.60</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
2	REMOVE & REINSTALL BOOTLID INNER GARNISH	New	100.00	0.00
3	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	900.00	200.00
4	RESPRAY PAINTING	New	1,000.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,150.00</b>	<b>650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >