



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 2951Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER HANDLE UPPER	USABLE	165.00	-
1	HANDLE BAR COMPLETE	NOT NECESSARY	120.00	-
1	SET HANDLE BAR BALANCER (END GRIPS)	REPLACED	60.00	60.00
1	SET WIND MIRROR	REPLACED	120.00	70.00
1	BRAKE LEVER LH	REPLACED	48.00	48.00
1	FRONT CENTRE PANEL	NOT NECESSARY	145.00	-
2	HEADLAMP COWLING LH / RH @\$167.50	N/S REPLACED	335.00	167.50
1	HEADLAMP ASSY (LED)	NOT NECESSARY	685.00	-
2	FRONT SIGNAL @\$86.00	NOT NECESSARY	172.00	-
2	FRONT FORK @\$410.00	NOT NECESSARY	820.00	-
1	FRONT MUDGUARD	REPLACED	110.00	110.00
1	FOOT BOARD LH	REPLACED	186.50	186.50
2	FOOREST BOARD LOWER SIDE COVER @\$128.60	N/S REPLACED	257.20	128.60
1	REAR MUDGUARD	REPLACED	158.60	158.60
1	CRANKCASE COVER	REPLACED	285.00	285.00
1	MUFFLER PROTECTOR	REPLACED	110.00	110.00
	LESS 10% DISCOUNT		-377.73	-132.42
			3,399.57	1,191.78
<u>SPECIAL NETT ITEMS</u>				
1	ERP IU UNIT (SN)	REPLACED	160.00	160.00
1	SET STEERING CONE BEARING (SN)	REPLACED	180.00	70.00
1	SET BODY STICKER (SN)	REPLACED	180.00	120.00
1	REAR BOX (SN)	REPLACED	350.00	220.00
1	SET REAR BOX RACK WITH BASE (SN)	REPLACED	180.00	150.00
			1,050.00	720.00
<u>LABOUR</u>				
	TOWING (2 TRIPS).	NOT NECESSARY	150.00	-
	STEERING STEM REPAIR & ALIGN.	NOT NECESSARY	200.00	-
	CHASSIS FRAME ALIGN.	NOT NECESSARY	550.00	-
	REAR RIM BALANCE.	NOT NECESSARY	120.00	-

Report Ref No. CS/LAW22010113/Tny3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WORKMANSHIP.		500.00	200.00
			1,520.00	200.00
GRAND TOTAL			5,969.57	2,111.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CS/LAW22010113/Tny3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.