



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 351L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER	TO REPAIR SEE LABOUR	481.10	-
1	FRT BUMPER UPPER MOULDING	SCRATCHED	368.50	368.50
1	FRT BUMPER SIDE BRACKET RH	NOT NECESSARY	35.00	-
10	FRT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	HEADLAMP RH	NOT NECESSARY	2,110.30	-
1	DAYLIGHT RH	NOT NECESSARY	642.50	-
1	DAYLIGHT GRILLE RH	SCRATCHED	93.45	93.45
	LESS 20% DISCOUNT		-750.57	-92.39
			3,002.28	369.56
LABOUR				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTINGS.	NOT NECESSARY	40.00	-
			740.00	600.00
GRAND TOTAL			3,742.28	969.56

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			750.00
---	--	--	---------------

Report Ref No. NS/INC22010130/Gncm4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.