



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9799U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT DOOR WING MIRROR ASSY LH	NOT NECESSARY	1,391.70	-
1	FRONT FENDER EMBLEM LH	NECESSARY	26.60	26.60
1	FRONT FENDER LH	BUCKLED	588.80	588.80
1	FRONT FENDER SHIELD LH	NOT NECESSARY	164.70	-
1	FRONT DOOR PANEL LH	NOT NECESSARY	1,797.20	-
1	WHEEL CAP RH	CUT	346.40	346.40
	LESS 20% DISCOUNT		-863.08	-192.36
			3,452.32	769.44
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT FENDER ADVERTISEMENT LH (SN)	NECESSARY	100.00	100.00
1	FRONT DOOR ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORT STICKER (SN)	NECESSARY	75.00	75.00
			275.00	275.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		550.00	350.00
	SPRAY PAINTING CHARGE.		700.00	500.00
	REMOVE/REFIX DOOR PARTS.	NOT NECESSARY	90.00	-
	RESET FRONT WHEEL ALIGNMENT.		90.00	60.00
	CHECK WIRING.	NOT NECESSARY	60.00	-
			1,490.00	910.00
<b>GRAND TOTAL</b>			<b>5,217.32</b>	<b>1,954.44</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,550.00</b>

Report Ref No. NS/INC22010131/Gvcm4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.