

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22010133/UPA3Q2**Date:** 15/12/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002222039
Claimant Vehicle No :	SLH8235C	Insured Vehicle No :	SJV3937T
Date of Loss:	11/10/2022	Nature of Claim:	TP
		Claim No:	202222007429KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH8235C	Engine No:	K14B1135785
Make & Model:	SUZUKI SWIFT, 1.4 (A)	Chassis No:	JSAFZC82S00333729
Reg. Date:	21/11/2016 (Man. Year: 2016)	Odometer:	162520 km
Colour:	White		
Engine Capacity:	1372 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,001.50	5,736.50	1,265.00	18.07
Miscellaneous Items	755.00	305.00	450.00	59.60
Labour	3,200.00	2,450.00	750.00	23.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,956.50	8,491.50	2,465.00	22.50
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	10,956.50	5,900.00	5,056.50	46.15
+ GST 7.00/7.00% (S\$)	766.96	413.00	353.96	46.15
Nett Amount (S\$)	11,723.46	6,313.00	5,410.46	46.15
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,115.00		

INSPECTION

Date of Assignment:	13/10/2022	Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	19/10/2022	Inspected At:	SME Motor Pte Ltd (Kaki Bukit)
			1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
			Singapore 417883
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2022)
Parts: 143	SUZUKI SWIFT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLH8235C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Distorted	560.00 F	*560.00 F
2	2		*REAR BUMPER RETAINER (WCP)	Bent	50.00 F	*50.00 F
3	10		*REAR BUMPER CLIPS (WCP)	Necessary	25.00 F	*25.00 F
4	1		*REAR BUMPER REINFORCEMENT (WCP)	Not fitted	225.00 F	*- F
5	1		*REAR END PANEL (WCP)	Badly Dented	350.00 F	*350.00 F
6	1		*REAR END PANEL TOP GARNISH (WCP)	Twisted	225.00 F	*225.00 F
7	6		*TOP GARNISH CLIPS (WCP)	Not Necessary	15.00 F	*- F
8	2		*REAR TAIL LAMP (WCP)	Cracked	480.00 F	*480.00 F
9	1		*FRT GRILLE (WCP)	Cracked	75.00 F	*75.00 F
10	1		*GRILLE CENTRE LOGO (WCP)	Scratched	25.00 F	*25.00 F
11	4		*GRILLE CLIPS (WCP)	Not Necessary	10.00 F	*- F
12	1		*FRT BUMPER (WCP)	Torn	480.00 F	*480.00 F
13	2		*FRT BUMPER RETAINER (WCP)	Bent	50.00 F	*50.00 F
14	10		*FRT BUMPER CLIPS (WCP)	Necessary	25.00 F	*25.00 F
15	1		*FRT BUMPER TOW COVER (WCP)	Missing	20.00 F	*20.00 F
16	1		*FRT BUMPER LOWER GRILLE (WCP)	Torn	85.00 F	*85.00 F
17	1		*FRT BUMPER REINFORCEMENT (TOP) (WCP)	Bent	365.00 F	*365.00 F
18	1		*FRT BUMPER REINFORCEMENT GARNISH (TOP) (WCP)	Distorted	230.00 F	*230.00 F
19	1		*AIRCON CONDENSER (WCP)	Punctured / Bent	585.00 F	*585.00 F
20	1		*RADIATOR (WCP)	Not Necessary	750.00 F	*- F
21	2		*HEADLAMP (WCP)	Cracked	900.00 F	*900.00 F
22	1		*CENTRE TOP PANEL (WCP)	Bent	150.00 F	*150.00 F
23	2		*HEADLAMP PANEL (WCP)	Repair	150.00 F	*- F
24	1		*FRT BONNET (WCP)	Dented /Buckled	535.00 F	*535.00 F

F=Franchise part.

Sub Total (S\$)	6,365.00	5,215.00
+ Margin on L,N Items 10.00/10.00% (S\$)	636.50	521.50
Total Parts (S\$)	7,001.50	5,736.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT NUMBER PLATE (CRACKED)	40.00	40.00
2	1	RADIATOR COOLANT (NECESSARY)	25.00	25.00
3	1	REAR NUMBER PLATE (BENT)	40.00	40.00
4	1	REVERSE CAMERA (NOT NECESSARY)	400.00	0.00
5	1	REVERSE SENSOR (SHORTED)	250.00	200.00
Sub Total (\$\$)			755.00	305.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	60.00
4	CAVITY PROTECTION ON ALL AFFECTED AREAS	New	150.00	60.00
5	LABOUR (REAR)	New	700.00	700.00
6	LABOUR (FRONT)	New	700.00	400.00
7	SPRAY PAINTING (REAR)	New	700.00	600.00
8	SPRAY PAINTING (FRT)	New	700.00	500.00
Gross Labour Cost (\$\$)			3,200.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >