



INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	XE5826R
Policy No:	DMCVSNW00099622200	Date of Loss:	07/10/2022
Vehicle Reg. No.:	<b>XE5826R</b>	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LBL CONSTRUCTION PTE. LTD.		
Driver:	KARUPPIAH ARIYAKKANNAN		
Make/Model:	MITSUBISHI FUSO, 10.7 D FV70HJD2VDEA (M)	Vehicle Reg. Date:	18/08/2020
Vehicle Colour:	White		
Engine No:	470912C0518410	Chassis No:	FV70HJA10001
Odometer:	0 KM		
Paint Type:			
Total Loss?	<b>YES</b>		
Est. Duration of Repair (day)	45		
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	28,770.54
Miscellaneous Items	4,100.00
Labour	8,900.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$)</b>	<b>41,770.54</b>
<b>+ GST 7.00% (\$)</b>	<b>2,923.94</b>
<b>Nett Amount (\$)</b>	<b>44,694.48</b>

This claim is handled by: LIEW SI MING



## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 18 Oct 2022)

**Parts:** N/A MITSUBISHI FUSO 10.7 D FV70HJD2VDEA (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Goldbell Engineering Pte Ltd/XE5826R/18/10/2022 11:31

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CHAMBER,NO.24-24SPG.	0.00	0.00	*395.00 F
2	2		*EXPANDER ASSY,FR BRAKE	0.00	0.00	*2,994.14 F
3	2		*O-RING,AIR CHAMBER	0.00	0.00	*10.30 F
4	1		*SENSOR,RR BRAKE PICKUP,LH	0.00	0.00	*300.00 F
5	2		*SPACER,RR BRAKE	0.00	0.00	*17.82 F
6	1		*SENSOR,RR BRAKE PICKUP,RH	0.00	0.00	*309.00 F
7	1		*COVER A ; DUST	0.00	0.00	*156.56 F
8	1		*MODULATOR ASSY,BRAKE	0.00	0.00	*3,902.04 F
9	1		*MODULATOR ASSY,BRAKE	0.00	0.00	*2,129.36 F
10	6		*JOINT,BRAKE AIR LINE,NO.5	0.00	0.00	*418.92 F
11	2		*JOINT,FRAME BRAKE AIR LINE,NO.4	0.00	0.00	*20.34 F
12	9		*JOINT,FRAME BRAKE AIR LINE,NO.4	0.00	0.00	*140.04 F
13	6		*JOINT,BRAKE AIR LINE,NO.5	0.00	0.00	*418.92 F
14	1		*SWITCH,BRAKE AIR LINE PARKING	0.00	0.00	*65.98 F
15	2		*JOINT,FRAME BRAKE AIR LINE,NO.4	0.00	0.00	*19.96 F
16	1		*CHAMBER ASSY ,FWD RR BRAKE,RH 24-24SPG (FP51SD)	0.00	0.00	*460.00 F
17	1		*COVER A ; DUST	0.00	0.00	*99.82 F
18	4		*SPRING,RR BRAKE SHOE RETURN	0.00	0.00	*343.44 F
19	4		*SPRING,RR BRAKE SHOE RETURN	0.00	0.00	*154.12 F
20	4		*SEAL,ACTUATOR	0.00	0.00	*71.08 F
21	8		*PIN,RETURN SPG,RR	0.00	0.00	*307.36 F
22	4		*CE RING	0.00	0.00	*13.24 F
23	2		*COVER PLATE	0.00	0.00	*23.86 F
24	2		*GROMMET	0.00	0.00	*187.94 F
25	12		*BOLT,FR BRAKE	0.00	0.00	*24.84 F
26	2		*OIL SEAL,RR WHEEL HUB,OTR	0.00	0.00	*29.52 F
27	2		*BEARING,RR WHEEL HUB,OTR	0.00	0.00	*397.50 F
28	2		*OIL SEAL,RR WHEEL HUB,INR (MOQ=2)	0.00	0.00	*105.06 F
29	2		*BEARING,RR WHEEL HUB,INR	0.00	0.00	*376.48 F
30	1		*BREATHER,RR AXLE HOUSING	0.00	0.00	*16.58 F
31	2		*GASKET,RR AXLE SHAFT	0.00	0.00	*8.38 F
32	1		*BUZZER,BACK	0.00	0.00	*390.75 F
33	1		*HARNES,CHASSIS	0.00	0.00	*11,629.56 F
34	1		*LAMP,COMBINATION,RR,RH	0.00	0.00	*93.70 F
35	1		*LINING KIT,RR BRAKE	0.00	0.00	*612.00 F
36	1		*TUBE ASSY,FRAME BRAKE AIR LINE	0.00	0.00	*580.14 F
37	1		*TUBE ASSY,FRAME BRAKE AIR LINE	0.00	0.00	*673.37 F
38	3		*TUBE,FWD RR AXLE BRAKE	0.00	0.00	*138.18 F
39	1		*TUBE,FRAME BRAKE AIR LINE,NO.16	0.00	0.00	*183.74 F
40	1		*TUBE,FRAME BRAKE AIR LINE,NO.16	0.00	0.00	*202.76 F
41	1		*TUBE,FRAME BRAKE AIR LINE,NO.8	0.00	0.00	*156.06 F
42	1		*CLIP,RR BRAKE	0.00	0.00	*105.44 F
43	1		*APRON, SPLASH	0.00	0.00	*87.24 F

F=Franchise part.

**Total Parts (\$\$)**

**28,770.54**

Goldbell Engineering Pte Ltd/XE5826R/18/10/2022 11:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	CANVAS MOTOR WIRING	400.00
2	1	CHENGAL TIMBER AT CHASSIS	600.00
3	4	REAR RH TYRES	1,800.00
4	1	SIDE CANVAS (GREEN) LH & RH	800.00
5	1	SIDE MUDGUARD LH & RH	500.00
<b>Sub Total (\$\$)</b>			<b>4,100.00</b>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	REMOVE AND REFIX BOTH SIDE MUDGUARD, BOTH SIDE CANVAS (GREEN), CANVAS MOTOR WIRING AND ALL CHENGAL TIMBER AT CHASSIS	New	1,500.00
2	TO PUTTY, CLEAN, SPRAY PAINT FOR REAR DECK	New	1,300.00
3	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN,ETC	New	4,500.00
4	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	New	800.00
5	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,900.00</b>

Goldbell Engineering Pte Ltd/XE5826R/18/10/2022 11:31. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**FUSO AIRMAN.**

**bizSAFE**  
S T R

